



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

211 Widney Road knowle Solihull
B93 9PS

Certificate No: 211 Widney Road knowle
Solihull B93 9PS

Engineers Details

Trading Title Coventry Gas Ltd

Address 47 Alspath Road
Meriden

Post Code: CV7 7LU

Gas Safe No: 526645

Telephone No: 07961768920

Installation Details

Installation Address 211 Widney Road , knowle ,Solihull , B93 9PS
211 Widney Road , knowle ,Solihull , B93 9PS
211 Widney Road , knowle ,Solihull , B93 9PS
211 Widney Road , knowle ,Solihull , B93 9PS

Post Code:

Telephone No:

Client Details

Client Address Colette Robinson
63 Langfield Road
Knowle

Post Code: B93 9PS

Telephone No: 07739637223

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen	Central Heating Boiler	Glow worm	Ultimate 70 FF	NA	NA	RS	YES	NA	YES	21.59 kw	YES	YES	YES	N/A	NO	YES
2	Kitchen	Hob	Hygena	Unknown	NA	NA	FL	YES	NA	YES	21 mb	YES	YES	NA	N/A	NO	YES
3	Lounge	Fire	Cannon	Caress 2000	NA	NA	OF	YES	NA	YES	NA mb	NO	YES	YES	N/A	NA	NO
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1	gas hob spark generator does not work	advised landlord	NO
2	gas fire was isolated previous to visit	none	NO
3			
4			
5			

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

3

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Tue-16-Aug-2022

Installation Pass:

YES

CO Alarm fitted & working?

NA

Smoke alarm fitted & working?

NA

Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Mon-16-Aug-2021

Report Received By:

Name:

Signed:

Date: Mon-16-Aug-2021

Gas ID Number: 4464997