



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

129 High Street

Certificate No: 129 High Street

Engineers Details

Trading Title: Coventry Gas Services

Address: 47 Alspath Road
Meriden

Post Code: CV7 7LU

Gas Safe No: 526645

Telephone No: 07961768920

Installation Details

Installation Address: 129 High Street Henley in Arden B95 5AU
129 High Street Henley in Arden B95 5AU
129 High Street Henley in Arden B95 5AU

Post Code: B955AU

Telephone No:

Client Details

Client Address: Wadsworth Solicitors
325 Stratford Road
Shirley
Solihull

Post Code: B903BL

Telephone No: 0121 745 8550

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Airing Cupboard	Central Heating Boiler	Servowarm	80/100C	NA	NA	OF	YES	NA	YES	NA kw	NO	YES	YES	FAIL	YES	NO
2																	
3																	
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1	burner has holes in it	requires new burner	YES
2	gas valve doesn't shut off correctly	needs new gas valve	YES
3	auto air vent leaking	needs new auto air vent	YES
4	main heat exchanger leaking	needs new main heat exchanger	YES
5	failed flue flow and spillage test	turned off immediately dangerous	YES

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

NO

Number of Appliances Tested:

1

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Sat-07-Nov-2020

Installation Pass:

YES

CO Alarm fitted & working?

NA

Smoke alarm fitted & working?

NA

Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Date: Thu-07-Nov-2019

Report Received By:

Name: Andrew King-Page

Signed:

Date: Thu-07-Nov-2019

Gas ID Number: 4464997