

Gas Service/Breakdown Record

Certificate Ref.
 16 Barlow Avenue 2025
 Certificate No 16 Barlow Avenue 2025

Installation Details		Client Details	
Installation Address:	Roger Gardner 16 Barlow Avenue Tamworth Postcode: B77 2FS	Client Address:	Roger Gardner 16 Barlow Avenue Tamworth Postcode: B77 2FS

Appliance Details		CO/CO2 Ratio:		Service:		Breakdown:		CO2 Reading:		CO Reading:	
Boiler Make:	Ideal	Boiler Model:	Logic Combi C30	Boiler Serial No:		Appliance Make:		Appliance Model:		Appliance Serial No:	

Preliminary Checks	Satisfactory	YES	NO	NA
Flue:Atmospheric/Fan assisted/Fan Dilution	YES			
Ventilation Size/H-L	YES			
Water/Fuel - Sound	YES			
Electrically Fused	YES			
Correct Valving Arrangement	YES			
Isolation Available - Electrical/Fuel (Within 1 metre)	YES			
Boiler/Plant room Clean & Clear	YES			
Service Checks	Satisfactory	YES	NO	NA
Heat Exchanger	YES			
Ignition	YES			
Gas Valve	YES			
Fan	YES			
Safety Device	YES			
Control Box	YES			
Burner & Pilot	YES			
Fuel Pressure & Type	YES			
Service Operations	Satisfactory	YES	NO	NA
Burner Washed & Clean				
Pilot Assembly Cleaned & Adjusted				
Ignition System Cleaned & Adjusted				
Burner Fan & Airways Cleaned				
Heat Exchanger/Flueways Clean & Clear				NA
Fuel & Electrical Supply Connected & Sound	YES			
Interlocks in Place				

Additional Notes
cleaned filter and condense trap

Spares Required
none

Engineers Details		Gas Safe Number		Time of Arrival:	
Trading Title:	Coventry Gas Services Ltd 47 Alspath Road Meriden Postcode: CV7 7LU	927997	5739462	09:42 am	
Report Issued By Name:	Andrew King-Page	Signature:		Date:	Mon-10-Feb-2025
Report Received By Name:		Signature:		Date:	Mon-10-Feb-2025