



Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out. This safety check complies with (but is not limited to) Regulation 26(9) of GSIUR.

Certificate Reference

22 Quensland 2025

Certificate No: 22 Quensland 2025

Engineers Details

Trading Title: Coventry Gas Services Ltd
Address: 47 Alspath Road
Meriden
Post Code: CV7 7LU
Gas Safe No: 927997
Telephone No: 07961768920

Installation Details

Installation Address: 22 Quensland
22 Quensland Avenue
Coventry
Post Code: CV5 8FG
Telephone No:

Client Details

Client Address: Surinder Sharma
5 Adkins Croft
Fillongley
Post Code: CV7 8PA
Telephone No: 447946467629

Appliance Details

Inspection Details

	Location	Appliance Type	Make	Model	CO2 Reading (%)	CO Reading (ppm)	Flue Type (OF/RS/FL)	Appliance Inspected (YES/NO/NA/IO) (IO = Visual Inspection Only)	Combustion Analysis Reading (CO/CO2)	Landlords Appliance (YES/NO/NA)	Operating Pressure(mbar) or Heat Input(kW)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen	Cooker	Currys	Essentials	NA	NA	RS	YES	NA	YES	21 mb	YES	YES	NA	N/A	NA	YES
2	Kitchen	Combi Boiler	Main	Combi 30 Eco Elite	9.0	90	RS	YES	0.0010	YES	29.47 kw	YES	YES	YES	N/A	YES	YES
3	Kitchen	Cooker	Currys	Essentials	NA	NA	RS	YES	NA	YES	19 mb	YES	YES	NA	PASS	NA	YES
4																	
5																	

Faults/Notes

Remedial Work Taken

Warning Notice Fixed

1	door on gas box missing	advised landlord	NO
2			
3			
4			
5			

Emergency Control Valve Accessible:

YES

Gas Tightness Satisfactory:

YES

Gas Installation Pipework Visual Inspection Satisfactory:

YES

Number of Appliances Tested:

3

Equipotential Bonding:

YES

NEXT INSPECTION DUE ON OR BEFORE:

Tue-20-Jan-2026

Installation Pass:

YES

CO Alarm fitted & working?

YES

Smoke alarm fitted & working?

YES

Signatures

Report Issued By:

Name: Andrew King-Page

Signed:

Gas ID Number: 5739462

Date: Mon-20-Jan-2025

Report Received By:

Name:

Signed:

Date: Mon-20-Jan-2025