

## Propane Tank Inspection Report

**Organization:** Demo Propane Company **Address:** 123 Industrial Blvd, Demo City, DC 12345

**Inspector:** Bruno Larizza **Compliance Mode:** US NFPA 58

### Executive Summary

Inspection completed successfully for TANK-001 at Main Facility - Building A. All safety systems are operational with no leaks detected. The tank system is in full compliance with US NFPA 58 standards.

### Inspection Overview


Date	Equipment ID	Location	Test Type	Result	Technician
January 20, 2025 at 04:00 AM	TANK-001	Main Facility - Building A	Leak Detection & Visual Inspection	PASS	Bruno Larizza

### Regulatory Compliance

- ✓ Leak Detection Test
- ✓ Visual Inspection
- ✓ Documentation Complete

✓ Inspector Certification Valid


### Inspector Signature

A rectangular box with a thin blue border, intended for the inspector's signature.

Bruno Larizza

Date: January 20, 2025 at 04:00 AM

### Digital Signature

A rectangular box with a thin blue border, intended for the digital signature.

Digitally Signed

Date: September 21, 2025 at 03:51 PM

---

This report certifies compliance with NFPA 58 standards for propane tank inspection.

Report generated by TankLog on September 21, 2025 at 03:51 PM