

Propane Tank Inspection Report

Organization: Demo Propane Company **Address:** 123 Industrial Blvd, Demo City, DC 12345

Inspector: Bruno Larizza **Compliance Mode:** CA TSSA

Executive Summary

Inspection completed successfully for TANK-004 at Remote Site - Location C. All safety systems are operational with no leaks detected. The tank system is in full compliance with CA TSSA standards.

Inspection Overview

Date	Equipment ID	Location	Test Type	Result	Technician
January 17, 2025 at 11:45 AM	TANK-004	Remote Site - Location C	Leak Detection & Visual Inspection	PASS	Bruno Larizza

Regulatory Compliance

- ✓ Leak Detection Test
- ✓ Visual Inspection
- ✓ Documentation Complete
- ✓ Inspector Certification Valid

Inspector Signature

Bruno Larizza
Date: January 17, 2025 at 11:45 AM

Digital Signature

Digitally Signed
Date: September 21, 2025 at 03:51 PM

This report certifies compliance with TSSA standards for propane tank inspection.

Report generated by TankLog on September 21, 2025 at 03:51 PM