

Window Project Punch List

General Observations

- ☐ many of the windows do not have the interior clips installed properly - or they do not work.
 - ☐ cannot open windows fully
 - ☐ the clips do not move to a state where you can open the window fully
- ☐ many of the windows have glue, caulking, or other debris on interior/exterior (see photos)
- ☐ need to have all Windows cleaned (interior/exterior)

Single-Pane Windows

- ☐ require holes to be patched, trimmed, and finished for smooth exterior consistent with the look of the interior finish for (8) windows
 - ☐ (1) small window above main entrance
 - ☐ (1) main window in study
 - ☐ (2) windows in upper staircase
 - ☐ (1) main window in master bath
 - ☐ (3) windows in great room

Kitchen Window (above sink)

- ☐ interior caulking requires fix/smoothing/touch-up
- ☐ Window has glue or caulking on interior glass
- ☐ left interior vertical has scratches on finish
- ☐ exterior window has glue on window trim
- ☐ left water vent is smashed
- ☐ caulking on interior wall (right)

Study Window #1 (south)

- ☐ right exterior water vent is bent/not installed properly
- ☐ exterior right trim has scratches
- ☐ window does not open fully

Study Window #2 (middle) Large Pane

- ☐ exterior: glue lower left corner
- ☐ interior holes

Study Window #3 (north)

- ☐ window does not open fully
- ☐ slips when opening near top

Main Entrance (Upper Short Window)

- ☐ shim not removed
- ☐ no caulking/finish

Dining Room/Porch Windows

- ☐ caulking on interior left wall
- ☐ middle window missing caulking/seal (left-side)
- ☐ left window does not open fully

Master Bath Large Pane Window

- ☐ exterior left trim has scratches
- ☐ interior not finished with caulking (all sides)
- ☐ drywall damage upper left
- ☐ lower-left exterior scratched
- ☐ interior holes need patching and finishing

Master Closet Window (Northwest corner)

- ☐ scratch damage on exterior trim
- ☐ exterior trim needs to be cleaned or has glue on right middle.
- ☐ Left water vent is not secure on the window

Master Bath Toilet Window

- ☐ Window does not open fully catches on clips
- ☐ glue on interior right trim
- ☐ exterior water vent is bent and not secure on window
- ☐ right exterior trim has glue

Master Bedroom Window (Northeast)

- ☐ lower exterior trim has caulking
- ☐ Screen has tear on right side
- ☐ glue on exterior upper window lower right side
- ☐ Exterior trim has scratch left window lower
- ☐ screen has caulking
- ☐ WINDOW DOES NOT OPEN PROPERLY
 - ☐ tilted and uneven
 - ☐ not in left/right track properly (not sized correctly)
 - ☐ window is too small for frame

Great Room Window (North)

- ☐ Window does not open properly or fully
- ☐ interior caulking

Great Room Window (South)

- ☐ does not open fully/properly
- ☐ caulking issues interior
- ☐ clips do not move

Great Room (Upper Windows)

- ☐ hail guard bent

Kitchen Sliding Door

- ☐ glue top exterior panel
- ☐ glue on handle
- ☐ exterior right window upper pane with scratch
- ☐ interior caulking issues
- ☐ drywall torn above door (middle)

Laundry Room Window

- ☐ exterior caulking clean up
- ☐ water vent bent/not sealing hole
- ☐ exterior left trim has glue
- ☐ missing interior guard/cap upper right

Garage Window (West)

- ☐ scratch on exterior left
- ☐ interior foam not finished
- ☐ need to remove shims

Garage Window (East)

- ☐ dirty screen/window
- ☐ exterior lower water vent not sealing/installed properly
- ☐ interior foam not finished

Staircase Lower Window

- ☐ caulking on wall
- ☐ holes require finish

Staircase Upper Window

- ☐ caulking on wall
- ☐ holes require finish

Upper Level Bath

- ☐ requires tile finish
- ☐ no interior caulking
- ☐ holes require finish

Upper Bedroom (Southeast)

- ☐ left window has gap and doesn't open properly