

Asset & Equipment Maintenance Log

Document No: **HARDWARE-2026-018**
Effective Date: 2026-02-09

1. Asset Identification	
Asset ID	9
Asset Name / Type	TP-Link Tapo-225
Model No.	router
Location	Data Center
IP Address	192.168.0.225
Criticality Level	High

2. Preventive Maintenance Schedule					
Task ID	Task Description	Frequency	Last Done	Next Due	Status
PM-001	System Health Check	Daily	2026-02-09	2026-02-10	☐ Done
PM-002	Performance Monitoring	Weekly	2026-02-09	2026-02-16	☐ Done
PM-003	Hardware Inspection	Monthly	2026-02-09	2026-03-11	☐ Done

3. AI Prediction Analysis - Corrective Maintenance Required	
Predicted Issue: AI Analysis Report for TP-Link Tapo-225: - System is operating normally - No critical issues detected	
Current Metrics:	
Confidence Score:	95%

4. Maintenance Checklist	
☐	Visual inspection of hardware components
☐	Check system temperature and cooling
☐	Verify network connectivity
☐	Test backup systems
☐	Review system logs for errors

Approval & Signatures

Technician Signature

Supervisor Signature