

Maintenance checks report

Checklist name	Year
Preventive Maintenance Year 7	7

Site	Turbine serial number	Order number
Wikinger	WK03 - 1121443	61160959
Language	Revision date checklist	Approval date
en-US	1/3/2025	2/11/2025

Siemens Gamesa Renewable Energy S.A. Parque Tecnológico de Bizkaia, Edificio 222, 48170, Zamudio, Vizcaya, Spain
+34 944 03 73 52 – info@siemensgamesa.com – www.siemensgamesa.com

1. Tools

Tools				
Group	#	Name	Calibration ID	Remarks
1	1	Hioki BT3554 (Dummy-Adw018)	https://secure.elementmetech.com/MIO3/dl?x=10B2C2660AADFA6F2G257248?2704407-1	

2. Check details

2.1. Checks from the maintenance plan

ECN				
AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
1	ATD000233.0: Rotor blade 1 - Oil level pitch gear - Inspection			✓
2	ATD000233.1: Rotor blade 2 - Oil level pitch gear - Inspection			✓
3	ATD000233.2: Rotor blade 3 - Oil level pitch gear - Inspection			✓
4	ATD000234.0: Rotor blade 1 - Pitch gear - Oil sample Barcode number on bottle 5651500			✓
5	ATD000234.1: Rotor blade 2 - Pitch gear - Oil sample Barcode number on bottle 5651501			✓
6	ATD000234.2: Rotor blade 3 - Pitch gear - Oil sample Barcode number on bottle 5651499			✓
7	ATD000236.0: Rotor blade 1 - Position indicators of the limit switches - Inspection			✓
8	ATD000236.1: Rotor blade 1 - Activation plate bolts of the limit switches - Test			✓
9	ATD000236.2: Rotor blade 1 - Support and joint elements of the limit switches - Inspection			✓
10	ATD000236.3: Rotor blade 2 - Position indicators of the limit switches - Inspection			✓
11	ATD000236.4: Rotor blade 2 - Activation plate bolts of the limit switches - Test			✓
12	ATD000236.5: Rotor blade 2 - Support and joint elements of the limit switches - Inspection			✓
13	ATD000236.6: Rotor blade 3 - Position indicators of the limit switches - Inspection			✓
14	ATD000236.7: Rotor blade 3 - Activation plate bolts of the limit switches - Test			✓
15	ATD000236.8: Rotor blade 3 - Support and joint elements of the limit switches - Inspection			✓
16	ATD000241.0: Rotor blade 1 - Blade bearing, pos. A - Grease sample Barcode number on bottle 3819470			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
17	ATD000241.1: Rotor blade 1 - Blade bearing, pos. B - Grease sample Barcode number on bottle 5651498			✓
18	ATD000241.2: Rotor blade 1 - Blade bearing, pos. C - Grease sample Barcode number on bottle 5651496			✓
19	ATD000241.3: Rotor blade 2 - Blade bearing, pos. A - Grease sample Barcode number on bottle 5651497			✓
20	ATD000241.4: Rotor blade 2 - Blade bearing, pos. B - Grease sample Barcode number on bottle 5651303			✓
21	ATD000241.5: Rotor blade 2 - Blade bearing, pos. C - Grease sample Barcode number on bottle 5651302			✓
22	ATD000241.6: Rotor blade 3 - Blade bearing, pos. A - Grease sample Barcode number on bottle 5651301			✓
23	ATD000241.7: Rotor blade 3 - Blade bearing, pos. B - Grease sample Barcode number on bottle 5651300			✓
24	ATD000241.8: Rotor blade 3 - Blade bearing, pos. C - Grease sample Barcode number on bottle 5651299			✓
25	ATD000242.00: Rotor system - Lubricant collector bottles - Inspection			✓
26	ATD000242.01: Rotor blade 1 - Lubricant collector bottles - Inspection and replace if level >50% Amount of replaced bottles +8			✓
27	ATD000242.02: Rotor blade 2 - Lubricant collector bottles - Inspection and replace if level >50% Amount of replaced bottles +8			✓
28	ATD000242.03: Rotor blade 3 - Lubricant collector bottles - Inspection and replace if level >50% Amount of replaced bottles +6			✓
29	ATD000243.0: Rotor blade 1 - External condition of the pitch cabinet - Inspection			✓
30	ATD000243.10: Rotor blade 1 - Wires and connectors of pitch drive converter and power supplies 26T1 and 26T5 - Inspection			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
31	ATD000243.11: Rotor blade 1 - Cabinet door closing clamp and general condition - Inspection			✓
32	ATD000243.12: Rotor blade 1 - Cabinet doors closed smoothly - Inspection			✓
33	ATD000243.13: Rotor blade 2 - Wires and connectors of pitch drive converter and power supplies 26T1 and 26T5 - Inspection			✓
34	ATD000243.14: Rotor blade 2 - Cabinet door closing clamp and general condition - Inspection			✓
35	ATD000243.15: Rotor blade 3 - Wires and connectors of pitch drive converter and power supplies 26T1 and 26T5 - Inspection			✓
36	ATD000243.16: Rotor blade 3 - Cabinet door closing clamp and general condition - Inspection			✓
37	ATD000243.17: Rotor blade 2 - Cabinet doors closed smoothly - Inspection			✓
38	ATD000243.18: Rotor blade 3 - Cabinet doors closed smoothly - Inspection			✓
39	ATD000243.1: Rotor blade 2 - External condition of the pitch cabinet - Inspection			✓
40	ATD000243.2: Rotor blade 3 - External condition of the pitch cabinet - Inspection			✓
41	ATD000243.3: Rotor blade 1 - Pitch drive converter, battery charger (leds), batteries, terminal connections of the batteries, connections of the cables to batteries, chopper resistor, starting resistor and grounding - Inspection			✓
42	ATD000243.4: Rotor blade 2 - Pitch drive converter, battery charger (leds), batteries, terminal connections of the batteries, connections of the cables to batteries, chopper resistor, starting resistor and grounding - Inspection			✓
43	ATD000243.5: Rotor blade 3 - Pitch drive converter, battery charger (leds), batteries, terminal connections of the batteries, connections of the cables to batteries, chopper resistor, starting resistor and grounding - Inspection			✓
44	ATD000243.6: Rotor blade 1 - Battery cabinet temperature - Measure Battery cabinet 1 temperature			✓
				+15.9 °C
45	ATD000243.7: Rotor blade 2 - Battery cabinet temperature - Measure Battery cabinet 2 temperature			✓
				+15.5 °C
46	ATD000243.8: Rotor blade 3 - Battery cabinet temperature - Measure Battery cabinet 3 temperature			✓
				+19.3 °C

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
47	ATD000243.9-1: Rotor blade 1 - Voltage and impedance of the batteries (exFO-S_0384) - Measure			
	1G22 / 8.1 impedance	+7.71 mΩ		
	1G22 / 8.1 voltage	+13.63 V		
	1G21 / 7.3 impedance	+8.09 mΩ		
	1G21 / 7.3 voltage	+13.68 V		
	1G20 / 7.2 impedance	+8.20 mΩ		
	1G20 / 7.2 voltage	+13.68 V		
	1G19 / 7.1 impedance	+8.05 mΩ		
	1G19 / 7.1 voltage	+13.69 V		
	1G18 / 6.3 impedance	+7.82 mΩ		
	1G18 / 6.3 voltage	+13.67 V		
	1G17 / 6.2 impedance	+8.07 mΩ		
	1G17 / 6.2 voltage	+13.65 V		
	1G16 / 6.1 impedance	+7.88 mΩ		
	1G16 / 6.1 voltage	+13.70 V		
	1G15 / 5.3 impedance	+8.51 mΩ		
	1G23 / 8.2 voltage	+13.65 V		
	1G23 / 8.2 impedance	+7.77 mΩ		
	1G24 / 8.3 voltage	+13.68 V		
	1G24 / 8.3 impedance	+7.99 mΩ		
	Temperature measured by Hioki	+15 °C		
	1G15 / 5.3 voltage	+13.55 V		
	1G14 / 5.2 impedance	+8.24 mΩ		

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
	1G14 / 5.2 voltage	+13.64 V		
	1G13 / 5.1 impedance	+8.24 mΩ		
	1G3 / 1.3 voltage	+13.65 V		
	1G2 / 1.2 impedance	+8.54 mΩ		
	1G2 / 1.2 voltage	+13.67 V		
	1G1 / 1.1 impedance	+8.54 mΩ		
	1G1 / 1.1 voltage	+13.67 V		
	1G30 / impedance	mΩ		
	1G29 / impedance	mΩ		
	1G28 / impedance	mΩ		
	1G27 / impedance	mΩ		
	1G26 / impedance	mΩ		
	1G25 / impedance	mΩ		
	1G3 / 1.3 impedance	+8.57 mΩ		
	1G4 / 2.1 voltage	+13.66 V		
	1G4 / 2.1 impedance	+7.66 mΩ		
	1G5 / 2.2 voltage	+13.65 V		
	1G13 / 5.1 voltage	+13.66 V		
	1G12 / 4.3 impedance	+7.86 mΩ		
	1G12 / 4.3 voltage	+13.48 V		
	1G11 / 4.2 impedance	+7.80 mΩ		
	1G11 / 4.2 voltage	+13.65 V		

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
	1G10 / 4.1 impedance	+7.84 mΩ		
	1G10 / 4.1 voltage	+13.64 V		
	1G9 / 3.3 impedance	+8.43 mΩ		
	1G8 / 3.2 impedance	+8.45 mΩ		
	1G8 / 3.2 voltage	+13.66 V		
	1G7 / 3.1 impedance	+8.16 mΩ		
	1G7 / 3.1 voltage	+13.68 V		
	1G6 / 2.3 impedance	+8.22 mΩ		
	1G6 / 2.3 voltage	+13.66 V		
	1G5 / 2.2 impedance	+9.01 mΩ		
	1G9 / 3.3 voltage	+13.67 V		
	Report other tool usage			
	No			
	New batteries?	No		
	Leakages	No		
	Hioki BT3554	Yes		
	Cracks	No		
	Bulks	No		
48	ATD000243.9-2: Rotor blade 2 - Voltage and impedance of the batteries (exFO-S_0384) - Measure			
	1G8 / 3.2 impedance	+9.07 mΩ		
	1G8 / 3.2 voltage	+12.95 V		
	1G7 / 3.1 impedance	+9.43 mΩ		
	1G7 / 3.1 voltage	+12.94 V		
	1G6 / 2.3 impedance	+9.35 mΩ		

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
	1G6 / 2.3 voltage	+12.94 V		
	1G5 / 2.2 impedance	+9.33 mΩ		
	1G5 / 2.2 voltage	+12.95 V		
	1G4 / 2.1 impedance	+9.40 mΩ		
	1G4 / 2.1 voltage	+12.93 V		
	1G3 / 1.3 impedance	+9.91 mΩ		
	1G3 / 1.3 voltage	+12.89 V		
	1G2 / 1.2 impedance	+8.90 mΩ		
	1G2 / 1.2 voltage	+12.95 V		
	1G1 / 1.1 impedance	+8.90 mΩ		
	1G9 / 3.3 voltage	+12.95 V		
	1G1 / 1.1 voltage	+12.93 V		
	1G9 / 3.3 impedance	+8.60 mΩ		
	1G10 / 4.1 impedance	+8.83 mΩ		
	1G18 / 6.3 voltage	+12.97 V		
	1G17 / 6.2 impedance	+8.34 mΩ		
	1G17 / 6.2 voltage	+12.96 V		
	1G16 / 6.1 impedance	+8.44 mΩ		
	1G16 / 6.1 voltage	+12.96 V		
	1G15 / 5.3 impedance	+8.45 mΩ		
	1G15 / 5.3 voltage	+12.96 V		
	1G14 / 5.2 impedance	+8.55 mΩ		

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
	1G14 / 5.2 voltage	+12.96 V		
	1G13 / 5.1 impedance	+8.81 mΩ		
	1G13 / 5.1 voltage	+12.95 V		
	1G12 / 4.3 impedance	+9.25 mΩ		
	1G12 / 4.3 voltage	+12.97 V		
	1G11 / 4.2 impedance	+8.31 mΩ		
	1G11 / 4.2 voltage	+12.93 V		
	1G10 / 4.1 voltage	+12.97 V		
	1G30 / impedance	mΩ		
	1G29 / impedance	mΩ		
	1G28 / impedance	mΩ		
	1G27 / impedance	mΩ		
	1G26 / impedance	mΩ		
	1G25 / impedance	mΩ		
	BSI (Battery Set Identifier), optional			
	1G18 / 6.3 impedance	+9.35 mΩ		
	1G19 / 7.1 voltage	+12.92 V		
	1G19 / 7.1 impedance	+9.36 mΩ		
	1G20 / 7.2 voltage	+12.99 V		
	1G24 / 8.3 impedance	+8.79 mΩ		
	1G24 / 8.3 voltage	+12.98 V		
	1G23 / 8.2 impedance	+8.58 mΩ		

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
	1G23 / 8.2 voltage	+12.98 V		
	1G22 / 8.1 impedance	+9.24 mΩ		
	1G22 / 8.1 voltage	+12.99 V		
	1G21 / 7.3 impedance	+8.93 mΩ		
	1G21 / 7.3 voltage	+12.98 V		
	1G20 / 7.2 impedance	+9.31 mΩ		
	Bulks	No		
	Hioki BT3554	Yes		
	New batteries?	No		
	Leakages	No		
	Cracks	No		
49	ATD000243.9-3: Rotor blade 3 - Voltage and impedance of the batteries (exFO-S_0384) - Measure			N/A
	1G15 / 5.3 voltage	+13.05 V		
	1G14 / 5.2 impedance	+8.84 mΩ		
	1G14 / 5.2 voltage	+13.06 V		
	1G13 / 5.1 impedance	+9.06 mΩ		
	1G13 / 5.1 voltage	+13.05 V		
	1G12 / 4.3 impedance	+8.75 mΩ		
	1G12 / 4.3 voltage	+13.07 V		
	1G11 / 4.2 impedance	+8.53 mΩ		
	1G11 / 4.2 voltage	+13.03 V		
	1G10 / 4.1 impedance	+9.01 mΩ		
	1G10 / 4.1 voltage	+13.07 V		

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
	1G9 / 3.3 impedance	+8.79 mΩ		
	1G9 / 3.3 voltage	+13.05 V		
	1G8 / 3.2 impedance	+9.26 mΩ		
	1G8 / 3.2 voltage	+13.05 V		
	1G15 / 5.3 impedance	+8.71 mΩ		
	1G16 / 6.1 voltage	+13.06 V		
	1G16 / 6.1 impedance	+8.79 mΩ		
	1G17 / 6.2 voltage	+13.06 V		
	Temperature measured by Hioki	Temperature measured by Hioki °C		
	1G24 / 8.3 impedance	+9.04 mΩ		
	1G24 / 8.3 voltage	+13.06 V		
	1G23 / 8.2 impedance	+8.73 mΩ		
	1G23 / 8.2 voltage	+13.07 V		
	1G22 / 8.1 impedance	+9.4 mΩ		
	1G22 / 8.1 voltage	+13.08 V		
	1G7 / 3.1 impedance	+9.56 mΩ		
	1G21 / 7.3 impedance	+9.02 mΩ		
	1G20 / 7.2 impedance	+9.49 mΩ		
	1G20 / 7.2 voltage	+13.08 V		
	1G19 / 7.1 impedance	+9.5 mΩ		
	1G19 / 7.1 voltage	+13.01 V		
	1G18 / 6.3 impedance	+9.55 mΩ		

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
	1G18 / 6.3 voltage	+13.07 V		
	1G17 / 6.2 impedance	+8.48 mΩ		
	1G21 / 7.3 voltage	+13.07 V		
	1G7 / 3.1 voltage	+13.04 V		
	1G6 / 2.3 voltage	+13..05 V		
	BSI (Battery Set Identifier), optional			
	1G5 / 2.2 impedance	+9.5 mΩ		
	1G5 / 2.2 voltage	+13.06 V		
	1G4 / 2.1 impedance	+9.63 mΩ		
	1G4 / 2.1 voltage	+13.05 V		
	1G3 / 1.3 impedance	+10.1 mΩ		
	1G3 / 1.3 voltage	+13 V		
	1G2 / 1.2 impedance	+9.1 mΩ		
	1G6 / 2.3 impedance	+9.55 mΩ		
	1G2 / 1.2 voltage	+13.07 V		
	1G1 / 1.1 voltage	+13.05 V		
	1G30 / impedance	mΩ		
	1G29 / impedance	mΩ		
	1G28 / impedance	mΩ		
	1G27 / impedance	mΩ		
	1G26 / impedance	mΩ		
	1G25 / impedance	mΩ		

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
	1G1 / 1.1 impedance	+9.03 mΩ		
	Bulks	No		
	Cracks	No		
	Hioki BT3554	Yes		
	Leakages	No		
	New batteries?	No		
50	ATD000277.0: Yaw system - Yaw gear A - Oil sample Barcode number on bottle	5651207		✓
51	ATD000277.10: Yaw system - Yaw gear F - Oil sample Barcode number on bottle	5651203		✓
52	ATD000277.12: Yaw system - Yaw gear G - Oil sample Barcode number on bottle	5605017		✓
53	ATD000277.14: Yaw system - Yaw gear H - Oil sample Barcode number on bottle	5605016		✓
54	ATD000277.2: Yaw system - Yaw gear B - Oil sample Barcode number on bottle	5651206		✓
55	ATD000277.4: Yaw system - Yaw gear C - Oil sample Barcode number on bottle	5651205		✓
56	ATD000277.6: Yaw system - Yaw gear D - Oil sample Barcode number on bottle	5651204		✓
57	ATD000277.8: Yaw system - Yaw gear E - Oil sample Barcode number on bottle	5651202		✓
58	ATD000278.0: Yaw system - Yaw gear A oil level - Measure Yaw gear A oil level before refill/drain Yaw gear A oil level in range?	+40 mm Yes, it was as needed		✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
59	ATD000278.1: Yaw system - Yaw gear B oil level - Measure Yaw gear B oil level before refill/drain +25 mm Yaw gear B oil level in range? Yes, it was as needed			✓
60	ATD000278.2: Yaw system - Yaw gear C oil level - Measure Yaw gear C oil level before refill/drain +50 mm Yaw gear C oil level in range? Yes, it was as needed			✓
61	ATD000278.3: Yaw system - Yaw gear D oil level - Measure Yaw gear D oil level before refill/drain +50 mm Yaw gear D oil level in range? Yes, it was as needed			✓
62	ATD000278.4: Yaw system - Yaw gear E oil level - Measure Yaw gear E oil level before refill/drain +35 mm Yaw gear E oil level in range? Yes, it was as needed			✓
63	ATD000278.5: Yaw system - Yaw gear F oil level - Measure Yaw gear F oil level before refill/drain +45 mm Yaw gear F oil level in range? Yes, it was as needed			✓
64	ATD000278.6: Yaw system - Yaw gear G oil level - Measure Yaw gear G oil level before refill/drain +50 mm Yaw gear G oil level in range? Yes, it was as needed			✓
65	ATD000278.7: Yaw system - Yaw gear H oil level - Measure Yaw gear H oil level before refill/drain +35 mm Yaw gear H oil level in range? Yes, it was as needed			✓
66	ATD000280.00: Rotor lock - Engagement holes - Inspection			✓
67	ATD000280.01: Rotor lock - Cylinders - Inspection			✓
68	ATD000280.02: Rotor lock - Pins - Inspection			✓
69	ATD000280.03: Rotor lock - Pins engaged - Inspection			✓
70	ATD000282.1: Rotor lock - Cylinders and hydraulic hoses - Inspection			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
71	ATD000282.2: Rotor lock - Sensor cables - Inspection			✓
72	ATD000283.0: Rotor brake - Callipers and drainage circuits - Inspection			✓
73	ATD000285.0: Rotor brake - Callipers - Test			✓
74	ATD000285.1: Rotor brake - Brake pads - Inspection			✓
75	ATD000286.0: Oil supply system - HG01, pos. 190.1 - Oil sample Barcode number on bottle			✓
		5651298		
76	ATD000297.0: Rotor brake - Rotor brake disk (360°) - Inspection			✓
77	ATD000297.1: Rotor brake - Brake disk (360°) wear - Inspection			✓
78	ATD000302.0: Yaw system - Lubricant collector bottles - Inspection and replace if level >75% Amount of replaced bottles			✓
		+0		
79	ATD000308.0: Yaw system - Gear grease collection tray - Inspection			✓
80	ATD000308.1: Yaw system - Bearing grease collection tray - Inspection			✓
81	ATD000309.0: Rotor brake - Drainage pipes - Inspection			✓
82	ATD000309.1: Rotor brake - Oil presence inside the drainage pipes - Inspection			✓
83	ATD000311.0: Wind turbine system - Emergency stop button at NC300 - Test			✓
84	ATD000311.1: Wind turbine system - Emergency stop button at NC320 - Test			✓
85	ATD000311.2: Wind turbine system - Emergency stop button at TBC300 - Test			✓
86	ATD000311.3: Wind turbine system - Emergency stop button at TBC00 - Test			✓
87	ATD000311.4: Wind turbine system - Emergency stop button at TBC202 - Test			✓
88	ATD000311.5: Wind turbine system - Emergency stop button at converter - Test			✓
89	ATD000311.7: Wind turbine system - Emergency stop button at TBC200 - Test			✓
90	ATD000313.0: Outer platform - Cooler platform - Inspection			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
91	ATD000319.0: Tower - Ground meshes between TP and S3 - Inspection			✓
92	ATD000319.1: Tower - Ground meshes between S3 and S2 - Inspection			✓
93	ATD000319.2: Tower - Ground meshes between S2 and S1 - Inspection			✓
94	ATD000335.0: Oil supply system - Magnets - Inspection			✓
95	ATD000339.00: Oil supply system - Whole structure - Inspection			✓
96	ATD000341.0: Oil supply system - Oil level - Measure Number of running pumps +0 Oil level +1050 l			✓
97	ATD000342.0: Yaw system - Trays - Inspection			✓
98	ATD000342.1: Yaw system - Trays - Clean			✓
99	ATD000355.0: Rotor brake - Hydraulic components of calliper 1 and 2 (right side) - Inspection			✓
100	ATD000355.15: Rotor brake - Seals around the callipers - Inspection			✓
101	ATD000355.1: Rotor brake - Hydraulic components of calliper 5 and 6 (left side) - Inspection			✓
102	ATD000355.2: Rotor brake - Hydraulic components of calliper 3 and 4 (upper side) - Inspection			✓
103	ATD000355.3: Rotor brake - Mechanical components of calliper 1 and 2 (right side) - Inspection			✓
104	ATD000355.4: Rotor brake - Mechanical components of calliper 5 and 6 (left side) - Inspection			✓
105	ATD000355.5: Rotor brake - Mechanical components of calliper 3 and 4 (upper side) - Inspection			✓
106	ATD000355.6: Rotor brake - Hoses and fittings of calliper 1 and 2 (right side) - Inspection			✓
107	ATD000355.7: Rotor brake - Hoses and fittings of calliper 5 and 6 (left side) - Inspection			✓
108	ATD000355.8: Rotor brake - Hoses and fittings of calliper 3 and 4 (upper side) - Inspection			✓
109	ATD000357.0: Rotor bearing - Seals - Inspection			✓
110	ATD000359.0: Hydraulic system - Hoses and fittings - Inspection			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
111	ATD000359.1 : Hydraulic system - Mechanical components - Inspection			✓
112	ATD000359.2 : Hydraulic system - All components - Inspection			✓
113	ATD000360.0: Hydraulic system - Hydraulic tank - Oil sample Barcode number on bottle	5605018		✓
114	ATD000361.0: Hydraulic system - Tank breather filter - Replace			✓
115	ATD000361.1: Hydraulic system - Pressure filters - Replace			✓
116	ATD000361.2: Hydraulic system - Return line filter - Replace			✓
117	ATD000362.0: Hydraulic system - Oil level - Inspection Oil level (before refill) Oil level in range?	+190 l Yes, it was as needed		✓
118	ATD000394.0: Generator cooling system - All pipelines, compensator, heat exchange and other components of both cooling units - Inspection			✓
119	ATD000394.1: Generator cooling system - All pumps, compensators, pipelines and other components of the midsection - Inspection	Remark 1 See annex 'Taken photos': 1 Remark 2 See annex 'Taken photos': 2 Remark 3 Dry coolant near pump stand and on valve joint , no wet leakage founded.		✓
120	ATD000394.2: Generator cooling system - All pipelines around generator - Inspection			✓
121	ATD000394.3: Generator cooling system - All pipelines around cellar - Inspection			✓
122	ATD000395.0: Installation system - TBC300 - Inspection			✓
123	ATD000395.1: Installation system - TBC202 - Inspection			✓
124	ATD000395.2: Installation system - TBC201 - Inspection			✓
125	ATD000395.3: Installation system - TBC200 - Inspection			✓
126	ATD000395.4: Installation system - TBC00 - Inspection			✓
127	ATD000395.5: Installation system - TBC200 switch drives for -20Q2M1, -21Q2M1 and -24Q2M1 - Inspection			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
128	ATD000398.0: Installation system - NC300 - Inspection			✓
129	ATD000398.1: NC300 - Electrical components and cable glands - Inspection			✓
130	ATD000398.2: Installation system - NC320 - Inspection			✓
131	ATD000398.3: NC320 - Electrical components and cable glands - Inspection			✓
132	ATD000401.0: Helicopter platform - Beacon 1 - Inspection			✓
133	ATD000401.1: Helicopter platform - Beacon 2 - Inspection			✓
134	ATD000401.2: Helicopter platform - Beacon 1 - Test			✓
135	ATD000401.3: Helicopter platform - Beacon 2 - Test			✓
136	ATD000405.0: Hydraulic accumulator - Rotor lock 570.1 - Measure Nitrogen pressures before refill +31 bar Nitrogen pressures at 50 ±2.5 bar? Yes, after refill			✓
137	ATD000405.10: Hydraulic accumulator - Yaw brake 740.4 - Measure Nitrogen pressures before refill +103 bar Nitrogen pressures at 120 ±2.5 bar? Yes, after refill			✓
138	ATD000405.12: Hydraulic accumulator - Rotor brake 920.1 - Measure Nitrogen pressures before refill +70 bar Nitrogen pressures at 90 ±2.5 bar? Yes, after refill			✓
139	ATD000405.14: Hydraulic accumulator - Rotor brake 920.2 - Measure Nitrogen pressures before refill +71 bar Nitrogen pressures at 90 ±2.5 bar? Yes, after refill			✓
140	ATD000405.16: Hydraulic accumulator - O-ring and connections - Inspection			✓
141	ATD000405.17: Hydraulic accumulator - Accumulator's body and connections - Inspection			✓
142	ATD000405.2: Hydraulic accumulator - Rotor lock 570.2 - Measure Nitrogen pressures before refill +31 bar Nitrogen pressures at 50 ±2.5 bar? Yes, after refill			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
143	ATD000405.4: Hydraulic accumulator - Yaw brake 740.1 - Measure Nitrogen pressures before refill +100 bar Nitrogen pressures at 120 ±2.5 bar? Yes, after refill			✓
144	ATD000405.6: Hydraulic accumulator - Yaw brake 740.2 - Measure Nitrogen pressures before refill +102 bar Nitrogen pressures at 120 ±2.5 bar? Yes, after refill			✓
145	ATD000405.8: Hydraulic accumulator - Yaw brake 740.3 - Measure Nitrogen pressures before refill +105 bar Nitrogen pressures at 120 ±2.5 bar? Yes, after refill			✓
146	ATD000425.0: NC300 - Bolts - Inspection			✓
147	ATD000425.1: NC320 - Bolts - Inspection			✓
148	ATD000426.0: TBC300 - Bolts - Inspection			✓
149	ATD000426.1: TBC202 - Bolts - Inspection			✓
150	ATD000426.2: TBC201 - Bolts - Inspection			✓
151	ATD000426.3: TBC200 - Bolts - Inspection			✓
152	ATD000426.4: TBC00 - Bolts - Inspection			✓
153	ATD000428.0: Ventilation system - Compensator between P1 & P2 - Inspection			✓
154	ATD000428.1: Ventilation system - Compensator on P3 - Inspection			✓
155	ATD000428.2: Ventilation system - Compensators (3) on P4 - Inspection			✓
156	ATD000428.3: Ventilation system - Compensator on P5 - Inspection			✓
157	ATD000429.0: Ventilation system - Motor 1 - Auditory inspection			✓
158	ATD000429.1: Ventilation system - Motor 2 - Auditory inspection	Remark 1 Not possible to switch on motor 2 by visu(opening only flap 1)		N/A

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
159	ATD000429.2: Ventilation system - Air intake humidity - Measure Air intake humidity +88 %			✓
160	ATD000429.3: Ventilation system - Differential pressure - Inspection Differential pressure +53 Pa			✓
161	ATD000443.0: Equipotential bonding systems - Yaw slip ring carbon brush 1 (mechanical part) - Inspection	Remark 1 Pressed by mistake, it's only one holder with stucked brush.		✓
162	ATD000443.1: Equipotential bonding systems - Yaw slip ring carbon brush 2 (mechanical part) - Inspection			✓
163	ATD000443.2: Equipotential bonding systems - Yaw slip ring carbon brush (mechanical part) 3 - Inspection	Remark 1 Brush stacked in holder See annex 'Taken photos': 3 Remark 2 Carbon brush stuck in holder		✓
164	ATD000443.3: Equipotential bonding systems - Yaw slip ring carbon brush 1 - Inspection and measure Carbon brush 1 length +64 mm			✓
165	ATD000443.4: Equipotential bonding systems - Yaw slip ring carbon brush 2 - Inspection and measure Carbon brush 2 length +64 mm			✓
166	ATD000443.5: Equipotential bonding systems - Yaw slip ring carbon brush 3 - Inspection and measure Carbon brush 3 length +64 mm	Remark 1 Can't measure as it's not possible to take out from holder		✓
167	ATD000445.0: Equipotential bonding systems - Heli deck handrail - Inspection			✓
168	ATD000445.1: Equipotential bonding systems - Nacelle grounding straps - Inspection			✓
169	ATD000445.2: Equipotential bonding systems - Upper nacelle lightning rods - Inspection	Remark 1 See annex 'Taken photos': 4 Remark 2 See annex 'Taken photos': 5 Remark 3 One lightning rod broken near holder Remark 4 SO 61867935 created		✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
170	ATD000445.3: Equipotential bonding systems - Lateral nacelle lightning rods - Inspection			✓
171	ATD000445.4: Equipotential bonding systems - Lower nacelle lightning rods - Inspection			✓
172	ATD000445.5: Equipotential bonding systems - Nacelle back side lightning rods - Inspection			✓
173	ATD000445.6: Equipotential bonding systems - Cellar platform lightning rods - Inspection			✓
174	ATD000445.7: Equipotential bonding systems - Grounding strap bolted connection - Inspection			✓
175	ATD000446.0: UPS - Surge arresters - Inspection			✓
176	ATD000446.2: Rotor blade 1 - VAL-MS 320/3+1/FM surge arrester of the pitch cabinet - Inspection			✓
177	ATD000446.3: Rotor blade 1 - PT 3-PB-ST surge arresters (x2) of the pitch cabinet - Inspection			✓
178	ATD000488.0: Rotor blade 1 - Bearing central lubrication system and elements - Inspection			✓
179	ATD000488.10: Rotor blade 3 - Bearing central lubrication pinion is greased - Inspection			✓
180	ATD000488.11: Rotor blade 3 - Bearing pinions area of work is greased - Inspection			✓
181	ATD000488.12: Blade bearing - Centralized lubrication system - Auditory inspection			✓
182	ATD000488.1: Rotor blade 1 - Grease tank for the blade bearing - Refill and reset strokes, if necesarry Grease level before refill +40 % Grease level in range? Yes, after refill			✓
183	ATD000488.3: Rotor blade 1 - Bearing central lubrication pinion is greased - Inspection			✓
184	ATD000488.4: Rotor blade 1 - Bearing pinions area of work is greased - Inspection			✓
185	ATD000488.5: Rotor blade 2 - Bearing central lubrication system and elements - Inspection			✓
186	ATD000488.6: Rotor blade 2 - Grease tank for the blade bearing - Refill and reset strokes, if necesarry Grease level before refill +40 % Grease level in range? Yes, it was as needed			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
187	ATD000488.8: Rotor blade 2 - Bearing central lubrication pinion is greased - Inspection			✓
188	ATD000488.9: Rotor blade 2 - Bearing pinions area of work is greased - Inspection			✓
189	ATD000493.0: Rotor system - Fan pitch converter 1 - Inspection			✓
190	ATD000493.1: Rotor system - Fan pitch converter 2 - Inspection			✓
191	ATD000493.2: Rotor system - Fan pitch converter 3 - Inspection			✓
192	ATD000497.00: Offline oil bypass - Filter cartridge - Replace			✓
193	ATD000498.0: Lightning current measurement system - Antennas and fixations - Inspection			✓
194	ATD000498.1: Lightning current measurement system - Control box - Inspection			✓
195	ATD000498.2: Lightning current measurement system - Lightning sensor system - Test	Remark 1 One antenna do not react on impuls(left). SO 61884455 created		✗
196	ATD000521.0: Converter - External coolers - Inspection			✓
197	ATD000521.2: Converter - Fans of the external coolers - Test			✓
198	ATD000551.0: Yaw system - Thickness of brake pad 1 - Measure Thickness of Svendborg brake pad 1 mm Thickness of Stromag brake pad 1 Green			✓
199	ATD000551.10: Yaw system - Thickness of brake pad 11 - Measure Thickness of Svendborg brake pad 11 mm Thickness of Stromag brake pad 11 Green			✓
200	ATD000551.11: Yaw system - Thickness of brake pad 12 - Measure Thickness of Svendborg brake pad 12 mm Thickness of Stromag brake pad 12 Green			✓
201	ATD000551.12: Yaw system - Thickness of brake pad 13 - Measure Thickness of Svendborg brake pad 13 mm Thickness of Stromag brake pad 13 Green			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
202	ATD000551.13: Yaw system - Thickness of brake pad 14 - Measure Thickness of Svendborg brake pad 14 mm Thickness of Stromag brake pad 14 Green			✓
203	ATD000551.14: Yaw system - Thickness of brake pad 15 - Measure Thickness of Svendborg brake pad 15 mm Thickness of Stromag brake pad 15 Green			✓
204	ATD000551.15: Yaw system - Thickness of brake pad 16 - Measure Thickness of Svendborg brake pad 16 mm Thickness of Stromag brake pad 16			✓
205	ATD000551.16: Yaw system - Thickness of brake pad 17 - Measure Thickness of Svendborg brake pad 17 mm Thickness of Stromag brake pad 17 Green			✓
206	ATD000551.17: Yaw system - Thickness of brake pad 18 - Measure Thickness of Svendborg brake pad 18 mm Thickness of Stromag brake pad 18 Green			✓
207	ATD000551.1: Yaw system - Thickness of brake pad 2 - Measure Thickness of Svendborg brake pad 2 mm Thickness of Stromag brake pad 2 Green			✓
208	ATD000551.2: Yaw system - Thickness of brake pad 3 - Measure Thickness of Svendborg brake pad 3 mm Thickness of Stromag brake pad 3 Green			✓
209	ATD000551.3: Yaw system - Thickness of brake pad 4 - Measure Thickness of Svendborg brake pad 4 mm Thickness of Stromag brake pad 4 Green			✓
210	ATD000551.4: Yaw system - Thickness of brake pad 5 - Measure Thickness of Svendborg brake pad 5 mm Thickness of Stromag brake pad 5 Green			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
211	ATD000551.5: Yaw system - Thickness of brake pad 6 - Measure Thickness of Svendborg brake pad 6 mm Thickness of Stromag brake pad 6 Green			✓
212	ATD000551.6: Yaw system - Thickness of brake pad 7 - Measure Thickness of Svendborg brake pad 7 mm Thickness of Stromag brake pad 7 Green			✓
213	ATD000551.7: Yaw system - Thickness of brake pad 8 - Measure Thickness of Svendborg brake pad 8 mm Thickness of Stromag brake pad 8 Green			✓
214	ATD000551.8: Yaw system - Thickness of brake pad 9 - Measure Thickness of Svendborg brake pad 9 mm Thickness of Stromag brake pad 9 Green			✓
215	ATD000551.9: Yaw system - Thickness of brake pad 10 - Measure Thickness of Svendborg brake pad 10 mm Thickness of Stromag brake pad 10 Green			✓
216	ATD000556.0: Hydraulic system - Valve 500 (Rotor lock applied) - Check pressure at MB Pressure at MB +40 bar			✓
217	ATD000556.1: Hydraulic system - Valve 490 (Rotor unlocked) - Check pressure at MA Pressure at MA +122 bar			✓
218	ATD000556.2: Hydraulic system - Valves 860.1 & 860.2 (Rotor brakes applied) - Check pressure at M2 and M4 and in Visu 900.1 & 900.2 (Hydratech) or 905.1 & 905.2 (Hydac) Pressure in Visu 900.1 (Hydratech) or 905.1 (Hydac) +92 bar Pressure in Visu 900.2 (Hydratech) or 905.2 (Hydac) +93 bar Pressure at M2 +92 bar Pressure at M4 +93 bar			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
219	ATD000556.3: Hydraulic system - Valve 670.1 and 670.2 (Pressure yaw brake 25% button activated) - Check pressure at M1 (750.1) & M3 (750.2) and 720.1 & 720.2 Pressure at M1 (750.1) Pressure at M3 (750.2) Pressure at 720.1 Pressure at 720.2			✓
220	ATD000556.4: Hydraulic system - Valves 320.1 and 320.2 (Valves 350.3, 350.4 and 350.5 closed and pump 1 running) - Check pressure at digital switch 360 Pressure at digital switch 360			✓
221	ATD000556.5: Hydraulic system - Valves 320.1 and 320.2 (Valves 350.3, 350.4 and 350.5 closed and pump 2 running) - Check pressure at digital switch 360 Pressure at digital switch 360			✓
222	ATD000556.6: Hydraulic system - Ball valves 290.1, 590 and 1080 - Inspection			✓
223	ATD000591.0: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing - Inspection			N/A
224	ATD000591.1: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing teeth involved - Inspection			N/A
225	ATD000591.2-10: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth -20 right side gap - Measure			N/A
226	ATD000591.2-11: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth -30 left side gap - Measure			N/A
227	ATD000591.2-12: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth -30 right side gap - Measure			N/A
228	ATD000591.2-1: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth left side gap - Measure			N/A
229	ATD000591.2-2: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth right side gap - Measure			N/A
230	ATD000591.2-3: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth +1 left side gap - Measure			N/A
231	ATD000591.2-4: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth +1 right side gap - Measure			N/A
232	ATD000591.2-5: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth -1 left side gap - Measure			N/A

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
233	ATD000591.2-6: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth -1 right side gap - Measure			N/A
234	ATD000591.2-7: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth -10 left side gap - Measure			N/A
235	ATD000591.2-8: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth -10 right side gap - Measure			N/A
236	ATD000591.2-9: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 1 - Blade bearing 0° tooth -20 left side gap - Measure			N/A
237	ATD000591.3: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing - Inspection			N/A
238	ATD000591.4: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing teeth involved - Inspection			N/A
239	ATD000591.5-10: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth -20 right side gap - Measure			N/A
240	ATD000591.5-11: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth -30 left side gap - Measure			N/A
241	ATD000591.5-12: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth -30 right side gap - Measure			N/A
242	ATD000591.5-1: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth left side gap - Measure			N/A
243	ATD000591.5-2: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth right side gap - Measure			N/A
244	ATD000591.5-3: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth +1 left side gap - Measure			N/A
245	ATD000591.5-4: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth +1 right side gap - Measure			N/A
246	ATD000591.5-5: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth -1 left side gap - Measure			N/A
247	ATD000591.5-6: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth -1 right side gap - Measure			N/A
248	ATD000591.5-7: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth -10 left side gap - Measure			N/A
249	ATD000591.5-8: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth -10 right side gap - Measure			N/A
250	ATD000591.5-9: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 2 - Blade bearing 0° tooth -20 left side gap - Measure			N/A
251	ATD000591.6: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing - Inspection			N/A
252	ATD000591.7: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing teeth involved - Inspection			N/A
253	ATD000591.8-10: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth -20 right side gap - Measure			

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
254	ATD000591.8-11: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth -30 left side gap - Measure			
255	ATD000591.8-12: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth -30 right side gap - Measure			
256	ATD000591.8-1: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth left side gap - Measure			N/A
257	ATD000591.8-2: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth right side gap - Measure			N/A
258	ATD000591.8-3: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth +1 left side gap - Measure			
259	ATD000591.8-4: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth +1 right side gap - Measure			
260	ATD000591.8-5: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth -1 left side gap - Measure			
261	ATD000591.8-6: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth -1 right side gap - Measure			
262	ATD000591.8-7: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth -10 left side gap - Measure			
263	ATD000591.8-8: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth -10 right side gap - Measure			
264	ATD000591.8-9: (WK09, WK10, WK32, WK45, WK46, WK49, WK69) Rotor blade 3 - Blade bearing 0° tooth -20 left side gap - Measure			
265	ATD000614.0: Rotor brake - Calliper 1 - Clean			✓
266	ATD000614.10: Rotor brake - Calliper 3 - Clean			✓
267	ATD000614.13: Rotor brake - Thickness of rotor brake pad calliper 3 (rotor side) - Measure Wear of rotor brake pad calliper 3 (rotor side) +0,2 mm Wear of rotor brake pad calliper 3 (rotor side) picture See annex 'Taken photos': 6			✓
268	ATD000614.14: Rotor brake - Thickness of rotor brake pad calliper 3 (generator side) - Measure Wear of rotor brake pad calliper 3 (generator side) +0,5 mm Wear of rotor brake pad calliper 3 (generator side) picture See annex 'Taken photos': 7			✓
269	ATD000614.15: Rotor brake - Calliper 4 - Clean			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
270	ATD000614.18: Rotor brake - Thickness of rotor brake pad calliper 4 (rotor side) - Measure Wear of rotor brake pad calliper 4 (rotor side) +0,2 mm Wear of rotor brake pad calliper 4 (rotor side) picture See annex 'Taken photos': 8			✓
271	ATD000614.19: Rotor brake - Thickness of rotor brake pad calliper 4 (generator side) - Measure Wear of rotor brake pad calliper 4 (generator side) +1,9 mm Wear of rotor brake pad calliper 4 (generator side) picture See annex 'Taken photos': 9			✓
272	ATD000614.20: Rotor brake - Calliper 5 - Clean			✓
273	ATD000614.23: Rotor brake - Thickness of rotor brake pad calliper 5 (rotor side) - Measure Wear of rotor brake pad calliper 5 (rotor side) +0,1 mm Wear of rotor brake pad calliper 5 (rotor side) picture See annex 'Taken photos': 10			✓
274	ATD000614.24: Rotor brake - Thickness of rotor brake pad calliper 5 (generator side) - Measure Wear of rotor brake pad calliper 5 (generator side) +1,85 mm Wear of rotor brake pad calliper 5 (generator side) picture See annex 'Taken photos': 11			✓
275	ATD000614.25: Rotor brake - Calliper 6 - Clean			✓
276	ATD000614.28: Rotor brake - Thickness of rotor brake pad calliper 6 (rotor side) - Measure Wear of rotor brake pad calliper 6 (rotor side) +1,95 mm Wear of rotor brake pad calliper 6 (rotor side) picture See annex 'Taken photos': 12			✓
277	ATD000614.29: Rotor brake - Thickness of rotor brake pad calliper 6 (generator side) - Measure Wear of rotor brake pad calliper 6 (generator side) +5,1 mm Wear of rotor brake pad calliper 6 (generator side) picture See annex 'Taken photos': 13			✓

AD 5-135_1_1_5_Preventive_year_null

#	Measuring points	Remarks	Tools	Status
Location:				
278	ATD000614.30: Rotor brake - Rotor brake, sensors fixations to the Beckhoff module - Inspection Module of the right side picture Ok Module of the left side picture Ok Module of the upper side picture Ok			✓
279	ATD000614.31: Rotor brake - Rotor brake pad, resistance of the connectors - Measure Resistance between pin 3 and 4 +0,68 Ohm Resistance between pin 1 and 2 +0,68 Ohm Resistance between pin 1 and 3 +109 Ohm Resistance between pin 1 and 4 +109 Ohm Resistance between pin 2 and 3 +109 Ohm Resistance between pin 2 and 4 +109 Ohm			✓
280	ATD000614.3: Rotor brake - Thickness of rotor brake pad calliper 1 (rotor side) - Measure Wear of rotor brake pad calliper 1 (rotor side) +1,5 mm Wear of rotor brake pad calliper 1 (rotor side) picture See annex 'Taken photos': 14			✓
281	ATD000614.4: Rotor brake - Thickness of rotor brake pad calliper 1 (generator side) - Measure Wear of rotor brake pad calliper 1 (generator side) +5,1 mm Wear of rotor brake pad calliper 1 (generator side) picture See annex 'Taken photos': 15			✓
282	ATD000614.5: Rotor brake - Calliper 2 - Clean			✓
283	ATD000614.8: Rotor brake - Thickness of rotor brake pad calliper 2 (rotor side) - Measure Wear of rotor brake pad calliper 2 (rotor side) +0,5 mm Wear of rotor brake pad calliper 2 (rotor side) picture See annex 'Taken photos': 16			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
284	ATD000614.9: Rotor brake - Thickness of rotor brake pad calliper 2 (generator side) - Measure Wear of rotor brake pad calliper 2 (generator side) +2,1 mm Wear of rotor brake pad calliper 2 (generator side) picture See annex 'Taken photos': 17			✓
285	ATD000615.0: Installation system - Emergency light of P7 - Test			✓
286	ATD000615.1: Installation system - Emergency light of P6 - Test			✓
287	ATD000615.2: Installation system - Emergency light of P5 - Test			✓
288	ATD000615.3: Installation system - Emergency light of P4 - Test			✓
289	ATD000615.4: Installation system - Emergency light of S2 and S1 - Test			✓
290	ATD000615.5: Installation system - Emergency light of P3 - Test			✓
291	ATD000615.6: Installation system - Emergency light of P2 - Test			✓
292	ATD000615.7: Installation system - Emergency light of P1 - Test			✓
293	ATD000615.8: Installation system - Emergency light of lower deck - Test			✓
294	ATD000615.9: Installation system - Emergency light of nacelle - Test			✓
295	ATD000638.0: Drive train system - Surface of the gearbox - Inspection			✓
296	ATD000638.10: Drive train system - Torque arms of the gearbox - Inspection			✓
297	ATD000638.12: Drive train system - Rotor hollow shaft and the center tube interface (from inside the hub) - Inspection			✓
298	ATD000638.13: Drive train system - Rotor bearing - Inspection			✓
299	ATD000638.5: Drive train system - Surface of the hollow shaft (from inside the hub) - Inspection			✓
300	ATD000638.7: Drive train system - O-ring between the gearbox housing and the callipers plate - Inspection			✓
301	ATD000638.8: Drive train system - O-ring between the brake disc and the callipers plate - Inspection			✓
302	ATD000642.0: Rotor blade 1 - Encoder, encoder support, wires, teeth and connector - Inspection			✓
303	ATD000642.1: Rotor blade 2 - Encoder, encoder support, wires, teeth and connector - Inspection			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
304	ATD000642.2: Rotor blade 3 - Encoder, encoder support, wires, teeth and connector - Inspection			✓
305	ATD000643.0: Hub - Central lubrication components - Inspection			✓
306	ATD000643.10: Rotor blade 2 - Lubrication pinion & pinion support - Inspection			✓
307	ATD000643.12: Rotor blade 3 - Lubrication pinion & pinion support - Inspection			✓
308	ATD000643.15: Rotor blade 2 - Central lubrication components - Auditory inspection			✓
309	ATD000643.16: Rotor blade 1 - Central lubrication components - Auditory inspection			✓
310	ATD000643.18: Rotor blade 2 - Lubrication system relief valve - Inspection			✓
311	ATD000643.19: Rotor blade 1 - Lubrication system relief valve - Inspection			✓
312	ATD000643.1: Rotor blade 1 - Grease tank for the blade gear rims - Refill and reset strokes, if necessary Grease level before refill +50 % Grease level in range? Yes, after refill			✓
313	ATD000643.5: Rotor blade 2 - Grease tank for the blade gear rims - Refill and reset strokes, if necessary Grease level before refill +40 % Grease level in range? Yes, after refill			✓
314	ATD000643.8: Rotor blade 1 - Lubrication pinion & pinion support - Inspection			✓
315	ATD000670.0: Lightning protection blade 1 - Sheath of LPS cable - Inspection			✓
316	ATD000670.1: Lightning protection blade 1 - Connection point of the LPS cable in the bearing - Inspection			✓
317	ATD000670.2: Lightning protection blade 1 - Bolted joint of the electrical connections - Inspection			✓
318	ATD000670.3: Lightning protection blade 2 - Sheath of LPS cable - Inspection			✓
319	ATD000670.4: Lightning protection blade 2 - Connection point of the LPS cable in the bearing - Inspection			✓
320	ATD000670.5: Lightning protection blade 2 - Bolted joint of the electrical connections - Inspection			✓
321	ATD000670.6: Lightning protection blade 3 - Sheath of LPS cable - Inspection			✓

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
322	ATD000670.7: Lightning protection blade 3 - Connection point of the LPS cable in the bearing - Inspection			✓
323	ATD000670.8: Lightning protection blade 3 - Bolted joint of the electrical connections - Inspection			✓
324	ATD000691.0: Brake disk - Upper grounding reels - Inspection			✓
325	ATD000691.1: Brake disk - Right grounding reels - Inspection			✓
326	ATD000691.2: Brake disk - Left grounding reels - Inspection			✓
327	ATD000692.0: Rotor blade 1 - Pitch motor brushes - Inspection			✓
328	ATD000692.10: Rotor blade 3 - Pitch motor brushes - Inspection			✓
329	ATD000692.11: Rotor blade 3 - Pitch motor brushes wear - Measure Length of the shortest carbon brush	+31 mm		✓
330	ATD000692.12: Rotor blade 3 - Pitch motor slip ring traces - Inspection			✓
331	ATD000692.1: Rotor blade 1 - Pitch motor brushes wear - Measure Length of the shortest carbon brush	+31.5 mm		✓
332	ATD000692.2: Rotor blade 1 - Pitch motor slip ring traces - Inspection			✓
333	ATD000692.5: Rotor blade 2 - Pitch motor brushes - Inspection			✓
334	ATD000692.6: Rotor blade 2 - Pitch motor brushes wear - Measure Length of the shortest carbon brush	+31.25 mm		✓
335	ATD000692.7: Rotor blade 2 - Pitch motor slip ring traces - Inspection			✓
336	ATD000693.0: Rotor blade 1 - Pitch motor collector room - Clean			✓
337	ATD000693.1: Rotor blade 2 - Pitch motor collector room - Clean			✓
338	ATD000693.2: Rotor blade 3 - Pitch motor collector room - Clean			✓
339	ATD000695.0: Rotor blade 1 - Pitch motor and gearbox - Inspection			✓
340	ATD000695.1: Rotor blade 2 - Pitch motor and gearbox - Inspection			✓
341	ATD000695.2: Rotor blade 3 - Pitch motor and gearbox - Inspection			✓

[32/32]

AD 5-135_1_1_5_Preventive_year_null				
#	Measuring points	Remarks	Tools	Status
Location:				
342	ATD000704.0: ventilation system - Drainage conduits on TP - Inspection			✓
343	ATD000704.1: ventilation system - Drainage conduits on P7 - Inspection			✓
344	ATD000704.2: ventilation system - Drainage conduits on P6 - Inspection			✓
345	ATD000704.3: ventilation system - Drainage conduits on P5 - Inspection			✓
346	ATD000704.4: ventilation system - Drainage conduits on P4 - Inspection			✓
Location: Tower				
347	ATD000704.5: Transition piece - Main transformer oil spill conduit and barrel - Inspection			✓
348	ATD000704.6: P7 - Main transformer oil spill conduit - Inspection			✓
Location:				
349	ATD000719.0: Air treatment system - Ball siphon valves - Inspection			✓
350	ATD000719.1: Air treatment system - Ball siphon valves - Test			✓

3. Annexes

3.1. Taken photos



1 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 119 - Remarks



2 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 119 - Remarks



3 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 163 - Remarks



4 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 169 - Remarks



5 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 169 - Remarks



6 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 267 - Measuring points



7 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 268 - Measuring points



8 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 270 - Measuring points



9 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 271 - Measuring points



10 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 273 - Measuring points



11 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 274 - Measuring points



12 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 276 - Measuring points



13 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 277 - Measuring points



14 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 280 - Measuring points



15 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 281 - Measuring points



16 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 283 - Measuring points



17 Figure from Checklist 'AD 5-135_1_1_5_Preventive_year_null', Task 284 - Measuring points