SnagAI - Construction Defect Report

AI-assisted site inspection

Inspection Details

Image file	pexels-pixabay-159358.jpg
Session ID	8a38ac53-2eb8-4caf-8e33-b7cc99756ef7
Analysed	2026-03-03T11:03:25.205634+00:00
Total issues	5

Site Photo

Issues Found (5)

#	Issue Type	Conf.	Location (bbox)
1	**Other Issue** *Exposed rebar sticking up from multiple columns without caps.*	95%	x=0.00 y=0.10 w=0.10 h=0.40
2	**Other Issue** *Loose rebar visible on the ground posing trip hazards.*	92%	x=0.40 y=0.30 w=0.20 h=0.40
3	**Other Issue** *Misaligned formwork with poor bracing visible at the top left.*	88%	x=0.00 y=0.00 w=0.20 h=0.20
4	**Other Issue** *Unsecured ladder being used by a worker without someone footing it.*	90%	x=0.20 y=0.60 w=0.10 h=0.30
5	**Other Issue** *Debris and waste material scattered on the construction site floor.*	87%	x=0.50 y=0.30 w=0.30 h=0.40