VEHICLE INSPECTOR Surveyor & Loss Assessor Portal


# DINESH KUMAR JANGIR

Surveyor & Loss Assessor

Licence No.: **SLA-121529** Validity: **26.01.2026**

**Mob. No.: 94132-24766**
10-RE-40, Tilak Nagar, Bhilwara (Raj.)
dk24766@gmail.com


TWO-WHEELER INSPECTION REPORT

## VEHICLE DETAILS

**Registration Number ***
RJ 06 WS 7400

**Odometer Reading (km) ***
63341

**Chassis Number ***
MBLHAW033K4B04445

**Engine Number ***
HA11ENK4B08296

**Name of Insured / Representative**
Jitendra Singh Rajput

**Relationship of Representative**
Self / Spouse / Son...

**Colour**
BKG

**Model Year**
2019

**Fuel Type**
Petrol

**Brand ***
Hero MotoCorp Ltd.

**Model ***
HF Deluxe

**Vehicle Type**
Motorcycle

**Engine CC / Battery Capacity**
97

**Variant (Optional)**

**Notes**

## VEHICLE PHOTOS

Click to add vehicle photos

Multiple images supported (JPG, PNG, etc.)







## VEHICLE CONDITION REPORT

Mark All Intact

Intact Missing Damaged N/A

| | | | | | |
|---|---|---|---|---|---|
| 1 | Wiser / Visor | ✓ Intact | Missing | Damaged | N/A |
| 2 | Head Lamp | ✓ Intact | Missing | Damaged | N/A |
| 3 | Fairing | ✓ Intact | Missing | Damaged | N/A |
| 4 | Front Panel | ✓ Intact | Missing | Damaged | N/A |
| 5 | Hub Nose | ✓ Intact | Missing | Damaged | N/A |
| 6 | Leg Shield | ✓ Intact | Missing | Damaged | N/A |
| 7 | Mudguard | ✓ Intact | Missing | Damaged | N/A |

| | | | | | |
|---|---|---|---|---|---|
| 8 | Shocker Left | ✓ Intact | Missing | Damaged | N/A |
| 9 | Shocker Right | ✓ Intact | Missing | Damaged | N/A |
| 10 | Indicator Lt | ✓ Intact | Missing | Damaged | N/A |
| 11 | Indicator Rt | ✓ Intact | Missing | Damaged | N/A |
| 12 | Rear View Mirror Left | ✓ Intact | Missing | Damaged | N/A |
| 13 | Rear View Mirror Right | ✓ Intact | Missing | Damaged | N/A |
| 14 | Fuel Tank | ✓ Intact | Missing | Damaged | N/A |
| 15 | Left Side Cover | ✓ Intact | Missing | Damaged | N/A |
| 16 | Left Running Board | ✓ Intact | Missing | Damaged | N/A |
| 17 | Left Side Rear Cowl | ✓ Intact | Missing | Damaged | N/A |
| 18 | Gear Shift Lever | ✓ Intact | Missing | Damaged | N/A |
| 19 | Foot Brake | ✓ Intact | Missing | Damaged | N/A |
| 20 | Left Foot Rest Front | ✓ Intact | Missing | Damaged | N/A |
| 21 | Left Foot Rest Rear | ✓ Intact | Missing | Damaged | N/A |
| 22 | Chain Cover | ✓ Intact | Missing | Damaged | N/A |
| 23 | Left Rear Shocker | ✓ Intact | Missing | Damaged | N/A |
| 24 | Saree Guard | ✓ Intact | Missing | Damaged | N/A |

| | | | | | |
|---|---|---|---|---|---|
| 25 | Engine Head | ✓ Intact | Missing | Damaged | N/A |
| 26 | Tail Lamp | ✓ Intact | Missing | Damaged | N/A |
| 27 | Left Rear Indicator | ✓ Intact | Missing | Damaged | N/A |
| 28 | Right Rear Indicator | ✓ Intact | Missing | Damaged | N/A |
| 29 | Rear Cowl | ✓ Intact | Missing | Damaged | N/A |
| 30 | Silencer | ✓ Intact | Missing | Damaged | N/A |
| 31 | Right Rear Shocker | ✓ Intact | Missing | Damaged | N/A |
| 32 | Right Foot Rest Rear | ✓ Intact | Missing | Damaged | N/A |
| 33 | Right Foot Rest Front | ✓ Intact | Missing | Damaged | N/A |
| 34 | Right Running Board | ✓ Intact | Missing | Damaged | N/A |
| 35 | Right Rear Cowl | ✓ Intact | Missing | Damaged | N/A |
| 36 | Right Side Cover | ✓ Intact | Missing | Damaged | N/A |

## DECLARATION

**DECLARATION OF OWNER**

I hereby confirm and declare that above mentioned identification of my vehicle as well as that of damage to the vehicle as noted by the inspection official is correct. Nothing has been hidden / undisclosed. I further confirm and declare that the motor vehicle proposed for insurance after a break in cover has not met with any accident giving rise to any claim by a third party for injury or death caused to any person or damages to any property/insured vehicle during the period following the expiry of the previous insurance, till the moment it is proposed for insurance.

I also agree that damages mentioned above shall be excluded / adjusted in the event of any claim being lodged.

Name & Sign of Proposer

Name & Sign of Surveyor

× Remove

(DINESH KUMAR JANGIR)

Name of Proposer

Jitendra Singh Rajput

Inspection Date

13-Mar-2026

Remarks

Stamp

Stamp

Save Vehicle Record | Print | Generate PDF

## SAVED VEHICLE RECORDS

© 2026. Built with ❤ using **caffeine.ai**