

CERTIFICATE OF EXAMINATION AND TEST

Certificate No: 82766 **Tag Number:** - **Status:** **SAFE**

Customer Details

Client: South Deep Gold Mine **Site:** Twin Shaft
Section: 100 Level

Asset Details

Asset ID: 40803 **Asset Tag No:** -
Equipment Type: Crane - Overhead/Bridge **Description:** 25 Ton FB Cranes DGEOTC
Serial No: 10386/2025 **Manufacturer:** FB Cranes

Asset Specifications

WLL: 25000 kg **Height of Lift:** 9000 mm
Span/Jib: 8250 mm **Permissible Deflection:** 11 mm
Hook Size: 150 mm **Steel Wire Rope:** 19 mm
Manufacture Date: 2025-11-29

Inspection Details

Inspection Type: LOADTEST **Inspection Date:** 2026-06-20
Certificate Expiry Date: 2027-06-20 **Inspector:** -

Inspection Photos




Photo 1

No Photo 2

Inspection Results

Criteria	Asset Value	Measured Value	Result	Remarks
WLL Main Hoist - Load Mass kg	25000	12000	RECORDED	Waterbag filled up to 12000kg only due to damages
WLL Auxiliary Hoist - Load Mass kg			RECORDED	
Permissible Deflection mm	11	10	RECORDED	
Hook Size mm	150	150	RECORDED	
Loadcell Number		fb25	RECORDED	
Load Limiter kg		12000	RECORDED	
Defects and Recommendations			RECORDED	None
Safe For Service			PASS	

Certification that the item has been inspected in accordance with the requirements of Driven Machinery and SANS Regulations and the responsible person has been informed of all defects.

Inspector Signature

Gauteng
 Cnr of Haring Rd & Snapper Rd,
 Woodville, Germiston, 1422
 011 902 3271

Rustenburg
 Unit 12A & B Platinum Business Centre,
 35 Ridder Street, East End, 0259
 014 596 5356
 info@fbcranes.co.za
 www.fbcranes.co.za