


Verizon Projects (2016-2017)


Complex Problem



Common Problem

OPTIX Application


Verizon Optix application was initially designed by the engineering team to resolve customer service network issues.




Conduent Project (2018-2019)

HIPAA Regulations & Privacy Concerns

According to HIPAA regulations and privacy concerns photography was not allowed in the mailrooms. Artist renderings were instead used to describe what the team has seen in the tour.




Camera
15 Sec Stop
before picture



X-Ray
Camera

Light box



Arm

Rejected Bin