



EMERGENCY LIGHT

EE Code: GPI 9 - EL-9-011

Location: Beside Rack 91A03 (3rd rack)

Date Inspecte 04/30/2024

Inspected by: R.Due

Finding: No light

Action: for JO to FEM for checking

Status:



EMERGENCY LIGHT

EE Code: EL-2-001

Location: GPI 2Main Entrance Gate 1

Date Inspecte 04/30/2024

Inspected by: K.Guevarra

Finding: No light

Action: for JO to FEM for checking

Status:



EMERGENCY LIGHT

EE Code: EL-2-005

Location: GPI 2 Office

Date Inspecte 04/30/2024

Inspected by: K.Guevarra

Finding: to return on its original location
(borrowed by FEM personnel)

Action: for JO to FEM

Status:

No Picture

Fire Alarm

EE Code: FA-2-006

Location: GPI 2: Office

Date Inspecte 04/30/2024

Inspected by: M.Mugas

Finding: to return the cover (used last Firedrill)

Action: for JO to FEM

Status: