



## ARROW AUTO BODY, INC

ARROWAUTOBODY@FRONTIER.COM  
808 W COLISEUM BLVD, FORT WAYNE, IN 46808  
Phone: (260) 482-6822  
FAX: (260) 482-4632

Workfile ID: 4c9ec068  
Federal ID: 35-2128232

### Preliminary Supplement 3 with Summary

**Customer: FICK, DENNIS**

**Job Number: FICK**

Written By: MELISSA  
Adjuster: BAILEY, CASEY, (888) 841-6467 x58288 Business

Insured: FICK, DENNIS  
Type of Loss:  
Point of Impact: 12 Front

Policy #:  
Date of Loss:

Claim #: 30005485112024  
Days to Repair: 0

**Owner:**  
FICK, DENNIS  
3307 ROSEWOOD DR  
FT WAYNE, IN 46804  
(260) 434-0771 Cell

**Inspection Location:**  
ARROW AUTO BODY, INC  
808 W COLISEUM BLVD  
FORT WAYNE, IN 46808  
Repair Facility  
(260) 482-6822 Business

**Insurance Company:**  
AUTO OWNERS INSURANCE

### VEHICLE

2017 BMW X3 xDrive28i Sports Activity Vehicle 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection blue

VIN: 5UXWX9C53H0T15726	Interior Color:	Mileage In: 78,696	Vehicle Out:
License:	Exterior Color: blue	Mileage Out:	
State:	Production Date:	Condition:	Job #: FICK

#### TRANSMISSION

Automatic Transmission  
4 Wheel Drive

#### POWER

Power Steering  
Power Brakes  
Power Windows  
Power Locks  
Power Mirrors  
Power Driver Seat  
Power Passenger Seat  
Memory Package

#### DECOR

Dual Mirrors  
Body Side Moldings  
Privacy Glass  
Console/Storage

Wood Interior Trim

#### CONVENIENCE

Air Conditioning  
Intermittent Wipers  
Tilt Wheel  
Cruise Control  
Rear Defogger  
Keyless Entry  
Alarm  
Message Center  
Steering Wheel Touch Controls  
Rear Window Wiper  
Telescopic Wheel  
Climate Control  
Parking Sensors  
Surround View Camera  
Home Link

#### RADIO

AM Radio  
FM Radio  
Stereo  
Search/Seek  
CD Player  
Auxiliary Audio Connection

#### SAFETY

Drivers Side Air Bag  
Passenger Air Bag  
Anti-Lock Brakes (4)  
4 Wheel Disc Brakes  
Traction Control  
Stability Control  
Front Side Impact Air Bags  
Head/Curtain Air Bags  
Communications System

Hands Free Device

#### SEATS

Bucket Seats  
Leather Seats

#### WHEELS

Aluminum/Alloy Wheels

#### PAINT

Clear Coat Paint

#### OTHER

Fog Lamps  
Rear Spoiler  
Signal Integrated Mirrors

#### TRUCK

Power Trunk/Liftgate

Get live updates at [www.carwise.com/e/4SqtFj](http://www.carwise.com/e/4SqtFj)

# Preliminary Supplement 3 with Summary

**Customer: FICK, DENNIS**

**Job Number: FICK**

2017 BMW X3 xDrive28i Sports Activity Vehicle 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection blue

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	<b>SPECIAL PRECAUTION</b>						
2	#	D&R BATTERY		1		0.2 M	
3	<b>FRONT BUMPER</b>						
4		Repl Add for park sensor		1		0.5	
5		Repl Add for fog lamps		1		0.3	
6	S01	O/H bumper assy				2.9	
7		Repl LT Bezel w/o X line	51117338513	1	77.28	Incl.	
8		Refn RT Lmp washer cover w/washer					0.2
9		Add for Clear Coat					0.1
10	*	S01 Rpr LT Lmp washer cover w/washer				<u>0.5</u>	0.2
11		S01 Add for Clear Coat					0.1
12		Repl Lower cover w/park sensor	51117389895	1	245.77	Incl.	
13		S01 Repl Bumper cover w/park assist, w/LED fog lamps w/surround	51117389903	1	1,087.47	Incl.	2.8
		Note: STARTING TO O/H BUMPER,INNER SUPPORT ON LT SIDE IS BROKEN OFF INNER COVER,AND HAS DAMAGE					
14		S01 Add for Clear Coat					1.1
15		S01 Add for h'lamp washer				0.4	
16		S01 Add for park sensor				0.5	
17		S01 Refn LT Lmp washer cover w/o washer					0.2
18		S01 Add for Clear Coat					0.1
19		S02 Repl LT Lmp washer cover w/washer	51117338568	1	58.67	0.1	0.2
20		S02 Add for Clear Coat					0.1
21		S02 Refn Park sensor outer					0.2
22		S02 Add for Clear Coat					0.1
23		S02 Refn Park sensor center					0.2
24		S02 Add for Clear Coat					0.1
25	<b>FRONT LAMPS</b>						
26		S01 Repl LT Fog lamp assy w/LED	63177317251	1	321.57	0.2	
27		S01 Aim fog lamps				0.3	
28		S01 Repl LT Washer nozzle	61677357001	1	125.08	0.3	
29		S01 Repl LT Headlamp assy w/adaptive lights	63117401141	1	2,051.47	1.2	
30		S01 Aim headlamps				0.5	
31	<b>FENDER</b>						
32	*	R&I LT R&I fender assy				<u>1.4</u>	
33		S01 Deduct for Overlap				-0.3	
34	*	S02 Rpr LT Fender assy				<u>7.0</u>	<u>2.2</u>
		Note: ALIGN TO HOOD AND STR AS NEEDED LABOR: Time includes fender liner, lower extension, wheel flare and side marker lamp.					
35		Add for Clear Coat					0.9
36		S02 Add for Edging					0.5
37		Repl LT Wheel flare w/o M package	51777210081	1	184.61	Incl.	

# Preliminary Supplement 3 with Summary

**Customer: FICK, DENNIS**

**Job Number: FICK**

2017 BMW X3 xDrive28i Sports Activity Vehicle 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection blue

38	S01	Repl	LT Finish molding	51117338569	1	59.73		
39		Repl	LT Front bracket	41357267325	1	63.39	0.2	0.3
40			Add for Clear Coat					0.1
41	S02	R&I	LT Fender liner front				Incl.	
42	S02	R&I	LT Fender liner rear				Incl.	
43	<b>WHEELS</b>							
44	S02	R&I	LT/Front R&I wheel			m	0.1	M
45	<b>VEHICLE DIAGNOSTICS</b>							
46	#	S01	Post - Scan		1	65.00	X	0.5 M
47	#	S03	OEM Diag Fee		1	69.95	X	
48	<b>MISCELLANEOUS OPERATIONS</b>							
49	#		Refn Test Spray Out					0.5
50	#		Feather edge prime and block		1		1.5	
51	#	S01	ADAS CALIBRATIONS - OPEN		1			
52	#		Subl Hazardous waste removal		1	8.00	X	
53	#		Cover Car Primer		1	10.00	0.2	
54	#		Cover Car Paint		1	10.00	0.2	
55	#		Repl Corrosion protection		1		T	0.3
56	#		Rpr COLOR SAND AND BUFF					1.0
57	#		Repl Flex additive		1	12.50	T	
58	#	S01	FINISH SAND & BUFF - COMPLETE PANEL		1			1.5
59	#	S01	ADAS CALIBRATIONS - OPEN		1			
			Note: HAS SURROUND VIEW					
60	#		MATCH INSURANCE ESTIMATE TO BUILD		1			
			Note: SUPPLEMENT.					
61	#	S01	clean,remove rust check jell from working area		1	10.00	1.5	
			Note: clean and degrease fender inside,door jams,engine compartment,and outside as needed all over,2 times to remove rust check,it does make paint fish eye real bad					
62	#	S02	Front Bumper Push Rivets		15	13.65		
			Note: stock					
63	#	S03	Subl Diagnose & Repair Front Camera		1	375.00	X	
64	#	S03	Subl BMW Calibrate Side View Camera		1	450.00	X	
65	#	S03	Subl BMW Seat Belt Check		1	37.50	X	
<b>SUBTOTALS</b>						<b>5,336.64</b>	<b>20.2</b>	<b>13.0</b>

## Preliminary Supplement 3 with Summary

**Customer: FICK, DENNIS**

**Job Number: FICK**

2017 BMW X3 xDrive28i Sports Activity Vehicle 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection blue

### ESTIMATE TOTALS

Category	Basis			Rate	Cost \$
Parts					4,318.69
Body Labor	19.4 hrs	@		\$ 65.00 /hr	1,261.00
Paint Labor	13.0 hrs	@		\$ 65.00 /hr	845.00
Mechanical Labor	0.8 hrs	@		\$ 100.00 /hr	80.00
Paint Supplies	13.0 hrs	@		\$ 45.00 /hr	585.00
Miscellaneous					1,017.95
Subtotal					8,107.64
Sales Tax	\$ 4,916.19	@		7.0000 %	344.13
<b>Grand Total</b>					<b>8,451.77</b>

**Preliminary Supplement 3 with Summary**

**Customer: FICK, DENNIS**

**Job Number: FICK**

2017 BMW X3 xDrive28i Sports Activity Vehicle 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection blue

**SUPPLEMENT SUMMARY**

Line		Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
<b>Added Items</b>								
47	#	S03	OEM Diag Fee		1	69.95 X		
63	#	S03	Subl Diagnose & Repair Front Camera		1	375.00 X		
64	#	S03	Subl BMW Calibrate Side View Camera		1	450.00 X		
65	#	S03	Subl BMW Seat Belt Check		1	37.50 X		
<b>SUBTOTALS</b>						<b>932.45</b>	<b>0.0</b>	<b>0.0</b>

**TOTALS SUMMARY**

Category	Basis	Rate	Cost \$
Parts			0.00
Miscellaneous			932.45
Subtotal			932.45
<b>Total Supplement Amount</b>			<b>932.45</b>
<b>NET COST OF SUPPLEMENT</b>			<b>932.45</b>

**CUMULATIVE EFFECTS OF SUPPLEMENT(S)**

Estimate	4,694.10	Dezi Lyons
Supplement S01	2,572.93	Dezi Lyons
Supplement S02	252.29	Donna Oswalt
Supplement S03	932.45	Donna Oswalt

**Job Total:** \$ **8,451.77**

A PERSON WHO KNOWINGLY AND WITH INTENT TO DEFRAUD AN INSURER FILES A STATEMENT OF CLAIM CONTAINING ANY FALSE, INCOMPLETE, OR MISLEADING INFORMATION COMMITS A FELONY.

**Customer: FICK, DENNIS**

**Job Number: FICK**

2017 BMW X3 xDrive28i Sports Activity Vehicle 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection blue

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide ERE1936, CCC Data Date 05/08/2025, and potentially other third party sources of data; and (b) the parts presented are OEM-parts. OEM parts are manufactured by or for the vehicle's Original Equipment Manufacturer (OEM) according to OEM's specifications for U.S. distribution. OEM parts are available at OE/Vehicle dealerships or the specified supplier. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships with discounted pricing. Asterisk (\*) or Double Asterisk (\*\*) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) items indicate manual entries.

Some 2024 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

**SYMBOLS FOLLOWING PART PRICE:**

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

**SYMBOLS FOLLOWING LABOR:**

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

**OTHER SYMBOLS AND ABBREVIATIONS:**

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. CFC=Carbon Fiber. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. STS=Stainless Steel. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Intelligent Solutions Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

## Preliminary Supplement 3 with Summary

**Customer: FICK, DENNIS**

**Job Number: FICK**

2017 BMW X3 xDrive28i Sports Activity Vehicle 4D UTV 4-2.0L Turbocharged Gasoline Gasoline Direct Injection blue

### PARTS SUPPLIER LIST

Line	Supplier	Description	Price
38	Zeigler Auto Group 4200 Parkway Pl SW Grandville MI 49418	#51117338569 LT Finish molding Quote: 2893859255 Expires: 11/12/24	\$ 59.73