




EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.885






EL image report




UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.885




Predicted Power Degradation: 0.885

Good Classification



Predicted Power Degradation: 0.885

Crack Classification






EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.885

Corrosion Classification



Small Corrosion Medium Corrosion Severe Corrosion