




EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.786





EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.786



EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.786

Good Classification



 Small Fault  Medium Fault  Severe Fault




EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.786

Crack Classification



Small Crack

Medium Crack

Severe Crack



EL image report



UNIVERSITY of
TASMANIA

Predicted Power Degradation: 0.786

Corrosion Classification



■ Small Corrosion ■ Medium Corrosion ■ Severe Corrosion