




# EL image report



UNIVERSITY of  
TASMANIA

Predicted Power Degradation: 0.932






# EL image report



UNIVERSITY of  
TASMANIA

Predicted Power Degradation: 0.932




# EL image report



UNIVERSITY of  
TASMANIA

Predicted Power Degradation: 0.932

Good Classification




 Small Fault     Medium Fault     Severe Fault

# EL image report

Predicted Power Degradation: 0.932

Crack Classification



 Small Crack     Medium Crack     Severe Crack




# EL image report



UNIVERSITY of  
TASMANIA

Predicted Power Degradation: 0.932

Corrosion Classification



Small Corrosion     Medium Corrosion     Severe Corrosion