

2026 HVAC and Related Work Order History

Document ID	WO-HISTORY-2026	Status	current
Effective date	2026-01-01	Owner	Facilities Service Desk

Document navigation

Page 2: Harbour Centre (Property A)

Page 3: Maple Square (Property B)

Page 4: River Tower (Property C)

Counts should distinguish corrective HVAC work orders from routine preventive maintenance.

Harbour Centre - Property A

Work order details

WO ID	Requested	Priority	Asset	Failure family	Summary
WO-A-1001	2026-01-07	P1	FCU-A-17	Airflow/Heating	No heat in east wing; fan motor tripped
WO-A-1014	2026-01-26	P1	FCU-A-17	Airflow/Heating	Fan coil stopped; motor overload reset
WO-A-1033	2026-02-18	P1	FCU-A-17	Airflow/Heating	Coil freeze and no airflow
WO-A-1051	2026-03-22	P1	FCU-A-17	Airflow/Heating	No airflow; fan motor failed again
WO-A-1060	2026-04-11	P3	AHU-A-02	Preventive Maintenance	Quarterly filter inspection

Maple Square - Property B

Work order details

WO ID	Requested	Priority	Asset	Failure family	Summary
WO-B-3001	2026-01-19	P3	RTU-B-03	Preventive Maintenance	Quarterly rooftop inspection
WO-B-3010	2026-02-11	P2	RTU-B-03	Controls	Thermostat calibration required
WO-B-3022	2026-03-06	P1	-	Water Leak	Domestic water leak in loading area

River Tower - Property C

Work order details

WO ID	Requested	Priority	Asset	Failure family	Summary
WO-C-2003	2026-01-12	P1	RTU-C-04	Compressor/Refrigerant	Low temperature; compressor lockout
WO-C-2021	2026-02-01	P1	RTU-C-04	Compressor/Refrigerant	Compressor lockout repeated
WO-C-2042	2026-03-15	P1	RTU-C-04	Compressor/Refrigerant	Low refrigerant and compressor trip
WO-C-2055	2026-04-03	P2	FCU-C-11	Condensate	Condensate drain blockage