



Subaru of Mississauga



QUALITY DRIVEN
PARTS & SERVICE

6160 Mavis Road, Mississauga, ON. L5V 2X4

Phone: 905-569-7777

Toll Free: 1-888-782-2785

Email: service@subarumiss.ca

www.subarumiss.ca

SO # 952333

Status WAITING

Printed 06/22/2026 4:46:11 PM

SERVICE ORDER CUSTOMER COPY



User kcro Page 1

Customer No 66239		Advisor HAILEY	Promised 06/22/2026 5:00 PM	Tag# x22
Mr Chao Yang Fang 1750 Bloor Street Unit # 401 Mississauga, ON L4X 1S9		Shop	Opened 06/22/2026 4:01 PM	Location
		Priority 123	Cashiered	PO #
Home (905) 206-9886	Bus (905) 333-0300	License DBYL242	Odom In 89782	Odom Out 89784
Cell (647) 291-5953	Today	Year 2017	Make SUBARU	Model OUTBACK
Email fchy5979@gmail.com		Vehicle ID No 4S4BSFNC3H3257250	Selling Dealer 01	Extended Warranty
Type	Term Cash	Engine 3.6L DOHC 24 Valve 6-Cylinder Boxer	Fleet #	Stock No 170300
				Colour LAPIS BLUE
				Delivery Date 10/22/2016

Request	Description	Job	CSR	Status
MCA	Service 'A' H4 2012+	1	476	Original

Labour	Description	Type	Hours	Amount
TMA	Service Maintenance A H4	CPQS	0.50	61.50

Replaced engine oil & oil filter.
Inspected & adjusted all fluid levels, including both differentials.
Inspected tire condition & adjusted tire pressures
Inspected operation of all lights, wipers & washers.
Inspected & adjusted Drive Belt tension.
Lubricated all Latches, Hinges & Locks.
Inspected Axle Boot Condition.
Visually Inspected Steering & Suspension Components.
Performed Battery test & reported on condition.
Check underbody for damage.
Complimentary- Exterior Vehicle Wash

NEXT	Your next service is due within 6 months or 99,000 kms (whichever comes first) Target Date: Dec, 2026.	CP	0.00	0.00
------	---	----	------	------

Part	Description	Shp	Bin	Type	Retail	Price	Amount
SCICAS0221100	GTX Magnatec 5W30	7		CRO	17.95	17.95	125.65
ENVIRO CHG	ENVIRONMENTAL FEE ENGINE OIL	7		CRO	0.22	0.22	1.54
ZENVIRONMENT	ENVRNMENT DISP/RCYL.	1		CRO	3.00	3.00	3.00
11126AA000	GASKET-DRAIN PLUG	1	47 H 1	CRO	1.91	1.91	1.91
15208AA031	*OIL FILTER(WAS 15208AA030)	1	36 C 3	CRO	16.75	16.75	16.75
ENVIRO CHG1	ENVIRONMENTAL FEE FILTER	1		CRO	0.50	0.50	0.50
ZPL-100	ANTI-FRICTION LUBRICANT	1		CRO	1.49	1.49	1.49
Technician	308 - BROOKE			Parts Total			150.84
Cause	Service A			Labour Total			61.50
				Request Sub-total			212.34

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON
STOCKED PARTS AFTER 30 DAYS.

NO REFUNDS OR EXCHANGE ON
ELECTRICAL ITEMS OR SPECIAL
ORDERS.

20% HANDLING CHARGE ON
ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE SUBARU PARTS & ACCESSORIES THAT ARE INSTALLED BY US ARE WARRANTED FOR 12 MONTHS OR 20,000KM'S, WHICHEVER OCCURS FIRST. (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS.) INQUIRE FOR FURTHER DETAILS. THE FACTORY WARRANTY CONSTITUTES ALL OF THE WARRANTIES WITH RESPECT TO THE SALE OF THIS ITEM/ITEMS. THE SELLER EXPRESSLY DISCLAIMS ALL WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THIS ITEM/ITEMS.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$_____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. **TERMS:** CREDIT CARD (Visa, MasterCard, AMEX), DEBIT CARD OR CASH UNLESS PRIOR ARRANGEMENTS MADE. A FINANCE CHARGE OF 2% PER MONTH(24% PER ANNUM MAY BE CHARGED ON OVERDUE ACCOUNTS.

DATE _____ CUSTOMER SIGNATURE _____ G.S.T. # R136642394



Subaru of Mississauga



QUALITY DRIVEN
PARTS & SERVICE

6160 Mavis Road, Mississauga, ON. L5V 2X4

Phone: 905-569-7777

Toll Free: 1-888-782-2785

Email: service@subarumiss.ca

www.subarumiss.ca

SO # 952333

Status WAITING

Printed 06/22/2026 4:46:11 PM

SERVICE ORDER CUSTOMER COPY



User

kcro

Page 2

Customer No 66239

Mr Chao Yang Fang
1750 Bloor Street Unit # 401
Mississauga, ON L4X 1S9

Home (905) 206-9886 Bus (905) 333-0300

Cell (647) 291-5953 Today

Email fchy5979@gmail.com

Type

Term Cash

Advisor	HAILEY	Promised	06/22/2026 5:00 PM	Tag#	x22
Shop		Opened	06/22/2026 4:01 PM	Location	
Priority	123	Cashiered		PO #	

License	DBYL242	Odom In	89782	Odom Out	89784	In Service Date	10/22/2016	Stock No	170300
Year	2017	Make	SUBARU	Model	OUTBACK	Model Number	HD2LE6	Colour	LAPIS BLUE
Vehicle ID No	4S4BSFNC3H3257250	Selling Dealer	01	Extended Warranty		Delivery Date	10/22/2016		
Engine	3.6L DOHC 24 Valve 6-Cylinder Boxer								Fleet #

Correction

- Engine oil & filter changed
- Hinges lubricated
- Tire pressures set to spec
- filters good (cabin/engine)
- Fluids topped up
- Service reminder set
- Vehicle road tested
- battery test:good
- winter tires:
- LF-8mm
- RF-8mm
- LR-8mm
- RR-8mm

Request	Description	Job	CSR	Status
maint-qs	Vehicle Walk Around - Maintenance Inspection Report	2	476	Approved

Save Time - Pre Book Your Next Service Appointment!!

Or Book On-Line: www.subarumiss.ca

Please take the time to complete your customer satisfaction survey from Subaru Canada

Labour	61.50
Parts	150.84
Supplies	9.99
Sub-Total	222.33
HST	28.90
Total Invoice	251.23

ALL CHARGES DUE UPON
RECEIPT OF STATEMENT.

NO REFUNDS OR EXCHANGE ON
STOCKED PARTS AFTER 30 DAYS.

NO REFUNDS OR EXCHANGE ON
ELECTRICAL ITEMS OR SPECIAL
ORDERS.

20% HANDLING CHARGE ON
ALL ACCEPTABLE RETURNS.

NO REFUNDS WITHOUT
THIS INVOICE.

ALL GENUINE SUBARU PARTS & ACCESSORIES THAT ARE INSTALLED BY US ARE WARRANTED FOR 12 MONTHS OR 20,000KM'S, WHICHEVER OCCURS FIRST. (EXEMPTING MAINTENANCE AND WEAR AND TEAR ITEMS.) INQUIRE FOR FURTHER DETAILS. THE FACTORY WARRANTY CONSTITUTES ALL OF THE WARRANTIES WITH RESPECT TO THE SALE OF THIS ITEM/ITEMS. THE SELLER EXPRESSLY DISCLAIMS ALL WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. THE SELLER NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF THIS ITEM/ITEMS.

INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$_____ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS INVOICE. **TERMS:** CREDIT CARD (Visa, MasterCard, AMEX), DEBIT CARD OR CASH UNLESS PRIOR ARRANGEMENTS MADE. A FINANCE CHARGE OF 2% PER MONTH(24% PER ANNUM MAY BE CHARGED ON OVERDUE ACCOUNTS.

DATE

CUSTOMER SIGNATURE

G.S.T. # R136642394

Vehicle Walk Around - Maintenance Inspection Report

Contact Chao Yang Fang
VIN 4S4BSFNC3H3257250

Tech BROOKE
Vehicle 2017 SUBARU OUTBACK

Completed Date 06/22/2026
Odom 89782

Fluid Levels

Engine Oil	Good	☒	☒	☒
Windshield Washer Fluid	Topped Up	☒	☒	☒
Coolant Level	Good	☒	☒	☒
Brake Fluid	Good	☒	☒	☒
Power Steering Fluid	N/A	☒	☒	☒
Transmission Fluid	Good	☒	☒	☒
Front Differential Fluid	Good	☒	☒	☒
Rear Differential Fluid	Good	☒	☒	☒
Coolant - Test Strength (B,C & D services)	Good to -30C	☒	☒	☒

Wiper Blades & Wiper Operation

Front - Driver Side Wiper Blade	Good	☒	☒	☒
Front - Passenger Side Wiper Blade	Good	☒	☒	☒
Rear - Tailgate	Good	☒	☒	☒
Windshield Washer Operation - Front	OK	☒	☒	☒
Windshield Washer Operation - Rear	OK	☒	☒	☒

Lights / Bulbs

Headlight -Driver Side high/low	Ok	☒	☒	☒
Headlight -Passenger Side high/low	Ok	☒	☒	☒
Taillight - Rear Right	Ok	☒	☒	☒
Taillight - Rear Left	Ok	☒	☒	☒
Rear Licence Plate Bulbs	Ok	☒	☒	☒
Rear - Reverse / Back Up / Brakes	Ok	☒	☒	☒
Marker Lights	Ok	☒	☒	☒
Interior- Dash Lights	Ok	☒	☒	☒
Interior - Dome / Map Lights	Ok	☒	☒	☒
Exterior - Convenience Lights	Ok	☒	☒	☒

Test Battery and Report

Battery Test & Report	Good	☒	☒	☒
-----------------------	------	-------------------------------------	-------------------------------------	-------------------------------------

Wheel Lock Key

Customer's Wheel Lock Key	N/A	☒	☒	☒
---------------------------	-----	-------------------------------------	-------------------------------------	-------------------------------------

General Items

Glass - Windshield & Windows	All Ok	☒	☒	☒
Axle Boot Inspection	Ok	☒	☒	☒
Steering & Suspension Components	Ok	☒	☒	☒
Drive Belt - Inspection and Check Tension	Ok	☒	☒	☒
Cooling System - Check Hoses and Clamps	Ok	☒	☒	☒
Leakage - Engine Oil	None - Dry	☒	☒	☒
Leakage - Coolant	None - Dry	☒	☒	☒
Leakage - Brake Fluid	None - Dry	☒	☒	☒
Leakage - Transmission Fluid	None - Dry	☒	☒	☒
Leakage - Power Steering Fluid	N/A	☒	☒	☒
Clutch Condition - If Applicable	N/A	☒	☒	☒
Engine - Air Filter	Ok	☒	☒	☒
Cabin Air Filter	Ok	☒	☒	☒
Vehicle Road Test	Completed - All	☒	☒	☒
Other Comments / Finding's :				

Check Tires - Winter - Adjust Tire Pressures - incl spare tire

Front Left - Drivers Side	Good: 5mm+	☒	☒	☒
Right Front - Pass Side	Good: 5mm+	☒	☒	☒
Right Rear - Pass Side	Good: 5mm+	☒	☒	☒
Left Rear - Drivers Side	Good: 5mm+	☒	☒	☒

Alignment

Alignment pass/fail	pass	☒	☒	☒
---------------------	------	-------------------------------------	-------------------------------------	-------------------------------------

Check Tires - Summer - Adjusted Tire Pressures - incl spare tire

Front Left -Dr Side	N/A	☒	☒	☒
Front Right - Pass Side	N/A	☒	☒	☒
Rear Right - Pass Side	N/A	☒	☒	☒
Left Rear - Dr Side	N/A	☒	☒	☒