

Agent Visual Inspection Disclosure

Inspection date: 2026-09-17

Agent Visual Inspection Disclosure — synthetic template modeled on the CAR AVID

Prepared for demonstration. SYNTHETIC DEMO DOCUMENT — fictional data for demonstration only. Not an official California Association of Realtors form.

Property address: 123 Main St, Pasadena, CA 91101

APN (Assessor's Parcel Number): 5842-018-024

Seller: Jane Seller

Inspection date: 2026-09-17

Weather / visibility: Clear, daylight

Participants present: Alex Agent, seller

Buyer present: _____

This disclosure records what the licensee observed by sight and sound during a walk-through. It is not a professional inspection, does not cover hidden or inaccessible conditions, and is not a warranty of condition. Items noted as not observed were inaccessible or outside the licensee's line of sight.

Walk-through participation

Participant	Role	Present
Jane Seller	Property owner	Yes
Alex Agent	Listing agent (observer)	Yes
(buyer)	Buyer	No
(buyer's agent)	Cooperating licensee	No

Areas inspected and observations

Area	Items observed / noted	Condition noted
Exterior — front	Stucco, front walkway, garage door	Serviceable
Yard / landscaping	Irrigation head misaligned at east bed	Minor defect noted
Driveway	Surface cracking near sidewalk joint	Cosmetic
Garage	Water heater strapped; panel clear	Serviceable
Entry / hall	Flooring intact; smoke alarm present	Serviceable
Living room	Ceiling and walls; window operation	No defects observed
Kitchen	Cabinets, sink, included appliances run	Operational
Dining area	Fixture, windows	No defects observed
Bedrooms (3)	Closets, windows, flooring	No defects observed
Bathrooms (2)	Vents, caulking, toilet stability	Minor caulk wear
Laundry area	Hookups, drain pan	Serviceable
Roof (from ground)	Composition shingles; gutters	Age visible; no active leak seen
Crawlspace access	Not opened during walk-through	Not observed
Systems (visible only)	Furnace filter slot; electrical panel	Serviceable

Not observed during this walk-through

- | | |
|--|---|
| ☒ Hidden structural components | ☒ Interior of walls or ceilings |
| ☒ Under-slab plumbing | ☒ Attic framing (not entered) |
| ☒ Septic or private systems | ☒ Radon, mold, or lab testing |

Notes and follow-up items

If the licensee later observes something additional, add it below and date the addition. Buyers should rely on their own inspections for conclusions about condition.

Buyer to order general home inspection and sewer scope.

Seller to provide roof repair receipt (2015 overlay) before closing.

Signatures (in order)

Alex Agent

Listing agent DRE Lic. #01874567

Date: 2026-09-17

Buyer

Date: _____

Jane Seller

Seller

Date: 2026-09-17

Demo Realty

Broker — Demo Realty DRE Lic. #01998765

Date: 2026-09-17