MOVE-IN CONDITION EVIDENCE

Surry hills


Tenant: Priya
Move-in date: 3 February 2026
Report created: 12/10/2026, 1:47:23 am (Sydney time)
Video: IMG_3688.mov, 00:51 long, recorded 12/10/2026, 1:45:24 am Sydney time (from the video's own metadata)
Video fingerprint (SHA-256): b762314d8860703fd7877f32c8a4d88f2864a587173ff4db60b14603b889f40e

This report records the condition of the room when the tenant moved in, using stills taken from the tenant's own video. Each still shows the time in the video it came from. The fingerprint above identifies the exact video file: keep the original video.
It adds to, and does not replace, the official condition report. In NSW the tenant must return the completed official condition report within 7 days of moving in. Attach this report to it.


Summary

- Good: 1 item
- Fair wear: 1 item
- Damaged: 2 items

Bedroom



door
Good
No visible damage
Video time 00:04 · seen via video and narration




wall near desk

Damaged

Chipped and peeling paint with visible wall damage

Video time 00:21 · seen via video and narration



lower wall behind desk

Fair wear

Marks and scuffs on lower wall near floor

Video time 00:35 · seen via video and narration



wall near mounted light

Damaged

Chipped paint patch and small marks on wall

Video time 00:45 · seen via video and narration

Confirmation

I, Priya, confirm that I filmed this video at the property on or around 3 February 2026 and that I reviewed each item in this report.

Signed: _____ Date: _____

Prepared with Bond Secure. Legal information, not legal advice.

Keep this PDF. If your bond isn't returned, upload it to Bond Secure and your evidence goes straight into your claim.