Mazda Digital Service Record



Vehicle Details

CX-5 - 2.2L SKYACTIV-D (184 hp) - SOUL RED 6AT Model - Engine - Transmission CRYSTAL M

JMZKFGW2A00812695

Contract Overview

27/03/2019 Italy Country of Origin Warranty Start Date

MOT Date

Contract Over view	
Mazda Europe Service Optional Extended Warranty Service Activated Warranty Used Car Warranty Service Plan	Standard cover expired - please discuss with your Mazda dealer No coverage No coverage No coverage No coverage
Next Scheduled Visit Due	
Adjusted Intervals	Please note: SKYACTIV Technology uses actual driving conditions to calculate the next required service and displays it on your vehicle's system. Wrench indication light will illuminate 1.000 km or 15 days before the necessary service". Estimation values below.
Service Intervals	Flexible maintenance indication the latest every 20.000 km (12.500 miles) or 12 months (whichever comes first) Your Manufacturer or Optional Extended Warranty may be affected if the recommended service schedule is not followed.
Next Scheduled Service Due	7th Service
Expected at	141009 Km or 15/11/2022
Latest at	141009 Km or 19/07/2023 (whichever comes first)

Previous Visits	Job Info	Odometer	Services Completed
MMI, UNICAR S.P.A. Via Cuneo 57 IT - 12062 Cherasco	19/07/2022 5M-1660	121009 Km	120.000 km / 75.000 miles / 72 months Body Inspection
MMI, MAZDA ALBA - UNICAR S.P.A. CORSO ASTI 24M IT - 12051 ALBA +390173311765	24/05/2022 MO/9177	110979 Km	Body Inspection
MMI, MAZDA ASTI - UNICAR S.P.A. CORSO ALESSANDRIA 529 IT - 14100 ASTI +390141476350	02/03/2022 M2-20344	98765 Km	100.000 km / 62.500 miles / 60 months Body Inspection

Mazda Digital Service Record



Previous Visits	Job Info	Odometer	Services Completed
MMI, UNICAR S.P.A. Via Cuneo 57 IT - 12062 Cherasco	29/11/2021 5M-1543	81740 Km	80.000 km / 50.000 miles / 48 months Body Inspection
MMI, UNICAR S.P.A. Via Cuneo 57 IT - 12062 Cherasco	12/07/2021 5M-1472	61660 Km	60.000 km / 37.500 miles / 36 months Body Inspection
MMI, UNICAR S.P.A. Via Cuneo 57 IT - 12062 Cherasco	04/02/2021 5M1391	39919 Km	40.000 km / 25.000 miles / 24 months Body Inspection
MMI, UNICAR S.P.A. Via Cuneo 57 IT - 12062 Cherasco	30/07/2020 5M/1288	19348 Km	20.000 km / 12.500 miles / 12 months Body Inspection
MMI, SEVEN SERVICE S.R.L. Corso Lombardia 58 IT - 10099 San Mauro Torinese	29/11/2019 265063	10301 Km	Body Inspection
MMI, SEVEN SERVICE S.R.L. Corso Lombardia 58 IT - 10099 San Mauro Torinese +390112731915	25/03/2019 245030	4 Km	PDI

Icon Legend



Additional Download Available



Visual Health Check



Renewal of Brake Fluid



Renewal of Cabin Air Filter



Renewal of Engine Air Filter



Renewal of Oil and Oil Filter



Renewal of Fuel Filter

My Mazda App

Did you know that you can see your service history and have a reminder for your next service always available in your phone? Download the My Mazda app to use these features and much more.

Android



iOS

