



RenovatorApp Inspection Report

Courtney's House

Inspection Date: 5/16/2026

Inspector: Mike Cavender

Property: 3604 Mission Montana Dr - San diego, CA 92120

Customer: Courtney Wilson

Townhouse

Bathroom

Rating: 3

Replace outlet

Estimate

Item	Cost	Hours
Outlet	\$5.00	0.5

Pictures



Bedroom

Rating: 4

Replace ceiling fan


Estimate

Item	Cost	Hours
Ceiling fan	\$150.00	2

Pictures



RenovatorApp Inspection Report



Summary

Total cost:	\$155.00
Total hours:	2.5



RenovatorApp Inspection Report

Parts List

Name	Cost
Ceiling fan	\$150.00
Outlet	\$5.00

Total parts cost:	\$155.00
-------------------	----------