



Republic of the Philippines
CAGAYAN DE ORO CITY
CITY PUBLIC SERVICES DEPARTMENT


25 August 2026

ENGR. JOEL V. MOMONGAN
City Engineer
Office of the City Engineer
Kauswagan, Cagayan de Oro City

Thru:

Engr. Albert Kate Dolores
Division Chief, PISD

Sir:



This pertains to the damaged PVC pipe at the male and female CR located at the 2nd floor legislative building of the City Hall.

Please be informed that as our personnel inspected the said area, it was assessed that it was beyond their capacity. Given the limited resources/equipment of this office, the undersigned humbly forward this matter to your office.

Please see attached picture below.

For your favorable response and appropriate action.

Thank you so much.

Very respectfully yours,

MERIE M. AGUSTERO
Officer-in-Charge
City Public Services Department

cc:

Vice Mayor Jocelyn Rodriguez
City Vice Mayor
Arturo S. de San Miguel
City Council