

EV Battery Health Assessment Report

EV Service Center - Certified Battery Diagnostics

Report Date: October 04, 2026

Report ID: RPT-23415

Vehicle: Hyundai Kona Electric - 2022

VIN: WVVZZZ3CZWE789012

Battery ID: B0007

Battery Parameters

Voltage:	3.21 V
Current:	1.78 A
Temperature:	42.1 C
Cycle Count:	155
Capacity:	1.32 Ah

Diagnostic Result

Status: SERVICE RECOMMENDED

Notes: Significant capacity degradation detected. Battery operating at elevated temperatures. Recommend immediate service evaluation and potential cell balancing procedure. Limit fast charging to emergency use only.

This report is generated by EV Battery Digital Twin diagnostic system.

For questions, contact your certified EV service center.