

JOBLING ACCIDENT REPAIR CENTRE LTD
SUNDERLAND STREET
SUNDERLAND
SR1 1UZ

Tel: 0191 5657291
Fax: 0191 5101683

Assessment Number: AJB14044
Version: connexus/2

Bodyshop Full Estimate Report
Printed: 06/07/2026

Addresses

Insured

Mrs Judith Atkins
1 Jesmond Road
Darlington
County Durham
DL1 3HN
Home Tel : 07881 817 819

Insurer

Exclusive Repair Network
Floor 2, St Georges House
56 Peter Street
Manchester
M2 3NQ
Home Tel : 0333 352 0779

Customer Message

Dear Customer,

We have pleasure in giving below our estimate for repairs to your vehicle. Full details of the estimated labour, paint and parts are attached.

Vehicle Details *
Calculations *

Yours sincerely,

Bodyshop Manager
This estimate has been produced using the Audatex System

* Note: The vehicle details and calculation sections are detailed below.

Vehicle Details

Vehicle

Manufacturer:	PEUGEOT
Model:	208 GT
Model Sheet Number:	B6I
Engine:	1.2 LTR 96KW
Registration Number:	BE57JDS
VIN Number:	VR3UPHNE2R4293713
Registration Month:	October
Registration Year:	2024
Odometer:	27310
Colour:	Yellow
Paint Code:	B0NEQ
Build Date:	FROM 10/2024
Selection Type:	AudaVIN+

Model Specs

FROM 10/2024
CONDENSER 20DM2 12MM
REFRIGERANT R1234YF
AUTO AIR CON
SIDE WINDOW/RR SCRNL
W-SCR W/O WEIGHT RED
WINDSCREEN ACOUSTIC
INN D/HANDLES CHROME
ELECT FOLDING MIRROR
DEAD LOCKS
PULSE GENERATOR
PASS WDW REGULAT PG
KEYLESS ENTRY/START
REAR ELECT WINDOWS
DOOR MIRROR PREMIUM
6 SPEAKER
S-WHEEL RADIO CONT
SHARK AERIAL
BI-TUNER
LED TAILLAMP

**JOBLING ACCIDENT REPAIR CENTRE LTD
SUNDERLAND STREET
SUNDERLAND
SR1 1UZ**

**Tel: 0191 5657291
Fax: 0191 5101683**

**Assessment Number: AJB14044
Version: connexus/2**

**Bodyshop Full Estimate Report
Printed: 06/07/2026**

AUTO HEADLAMP LEVEL
AUTO DIP/DRIVE LIGHT
LED HEADLAMP
NO PLATE LAMP
ULTRASONIC PARK SYS
HEIGHT ADJ PASS SEAT
PEDAL CARRIER ALU
W-SCREEN TINT W/SEAL
WINDSCREEN W/SENSOR
AUTO DIPPING MIRROR
ROOD CONSOLE 3-LED
SIDE INNER LIGHT
S/BELT W/WARNING DEV
CHILD SEAT MOUNTING
ILLUM SUN VISORS
COMBI INSTRUMENT 3D
ANTI THEFT ALARM
THATCHAM SECURITY
KOMPRSSOR BADGE
AIR GUIDE ADJUSTABLE
FUEL TANK 44 LTR
RAD 21DM2 18MM
EMISSIONS EURO 6.4
DISPLAY 10" HD
PAINTED DOOR HANDLES
FRT FLOOR LWR DEFLEC
W-HOUSE ACOUST LINER
FIREWALL INSULATION
1.2 LTR 96KW
GEARBOX 6 SPEED
FRT STABI 21.5MM
ELECTRIC HAND BRAKE
FRT BRAKE DISC 283MM
EXHAUST CURVE 3.1
ESP
REAR AXLE 30000N.M
FRT AXLE SUPP STEEL
AUTOMATIC BRAKE SYS
ELECT POWER STRG 83A
F W/BEARING 78 MM
REAR DISC BRAKE
TYRES 205/45 HR 17
WHEELS 7J X 17 ALLOY
CHECK BATTERY CHARGE
BATTERY 70AH EFBC
ELECTRIC FAN 140W
ALTERNATOR 120A
SPARE WHEEL
FRT HEAD/SIDE AIRBAG
EQUIPMENT GT
FRT/RR BUMP DESIGN 3
STARTER MOTOR STTD

**JOBLING ACCIDENT REPAIR CENTRE LTD
SUNDERLAND STREET
SUNDERLAND
SR1 1UZ**

**Tel: 0191 5657291
Fax: 0191 5101683**

**Assessment Number: AJB14044
Version: connexus/2**

**Bodyshop Full Estimate Report
Printed: 06/07/2026**

STOP-START SYSTEM
REAR SPOILER
RAD GRILLE YELLOW
WING EXTENSION
DOOR MOULDINGS BLACK
PRODUCTION SPAIN
PAINTING OFF VEHICLE
FACELIFT
THREE COAT PEARL

JOBLING ACCIDENT REPAIR CENTRE LTD
SUNDERLAND STREET
SUNDERLAND
SR1 1UZ

Tel: 0191 5657291
Fax: 0191 5101683

Assessment Number: AJB14044
Version: connexus/2

Bodyshop Full Estimate Report
Printed: 06/07/2026

Extras			
Description		Betterment	Price
O/S/R ALLOY REFURB	Specialist	0%	£162.00
BSI COMPLIANCE	Specialist	0%	£34.00
METHODS RESEARCH	Specialist	0%	£37.00
E.P.A. CHARGE	Specialist	0%	£25.00
ARIES CERT	Specialist	0%	£21.00
RECOVERY	Specialist	0%	£180.00
CAR CARE KIT	Specialist	0%	£8.00
ADAS METHODS	Specialist	0%	£31.00
ENERGY PAYMENT	Specialist	0%	£25.00
TRANS TO SPEACILIST	REFURB	0%	£64.00
TRANS FROM SPEACIAL	REFURB	0%	£64.00
Total Extras			£651.00

Calculation

11/06/2026

Labour			
	Total Panel/Mechanical	£1,049.60	
	Total Paintwork	£830.72	
Total Labour			£1,880.32
Total Paint/Material			£1,162.96
Costs			
Total Parts			£488.88
Additional Costs			
	Cost of Specialist	£651.00	
Total Additional Costs			£651.00
Grand Total Excl VAT			£4,183.16
	VAT @ 20 %		£836.63
Grand Total Incl VAT			£5,019.79
	Excess		£0.00

Repair Information

LABOUR		Time Basis 10 WU = 1 HR. Price = £64.00/HR
Repair / Guide		
Number	Description	Work Units
35.E42A	ALIGN FRONT AXLE AND REAR AXLE BEFORE REPAIR	12.0

93.EIMA	R + R RIGHT REAR DOOR TRIM	2.0
90.EV8A)	R + R R/R DOOR TRIM	4.0
90.EH0A)	R + R R/R OUTER DOOR HANDLE	5.0
92.E5CA	R + R R/R OUTER DOOR CHANNEL MOULDING	2.0
63.E2RA	R + R L/R NUMBER PLATE LAMP	2.0
74.EA5A	RENEW R/R WING BADGE	2.0
74.EJ2A	R + R REAR BUMPER	7.0
	INCLUDES: R + R TAILLAMPS	
NO NUMBER	REMOVE AND REFIT REAR BUMPER SKIRT	2.0
74.E3VS)	R + R REAR BUMPER R/UPPER BRACKET	1.0
	O/S/R TYRE 205/45R17	
	PANEL REPAIR SUNDRIES	
	DECALS Renew	
1000	REMOVE&REFIT SWAP SPARE WHEEL	5.0*
2583	REPAIR REAR BUMPER	5.0*
3482	REPAIR R/R WING	30.0*
3688	REPAIR R/R WING EXTENSION	5.0*
1000	ESTIMATE PRE CLEAN	5.0*
1000	CHECK EV RISK ASSESS	5.0*
1000	CHECK SHUTDOWN VEHICLE	30.0*
1000	CHECK AND CLEAN CAR	5.0*
1000	CHECK AND QUALITY CONTROL	5.0*
1000	CHECK AND ROAD TEST	5.0*
1000	CHECK VEH DIAG PRE CHECK	10.0*
1000	CHECK VEH DIAG POST CHECK	10.0*
1000	CHECK ADAS IDENTIFICATION	5.0*

Total Work Units	164.0
Total Panel / Mechanical Labour	16.40 HRS £1,049.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = £64.00/HR

Repair /Guide	Description	Work Units
Number		
2583	REAR BUMPER REPAIR PAINT PLASTIC	17.6
3482	R/R WING REPAIR PAINTING <50%	16.0
3688	R/R WING EXTENSION REPAIR PAINT PLASTIC	11.9
1822	R/R DOOR W/O FRAME SURFACE PAINT	9.1
1866	R/R DOOR OUT HANDLE SURFACE PAINT PLAST.	4.5
2102	R/SILL PANEL SURFACE PAINT	7.5
2354	R/ROOF RAIL SURFACE PAINT	6.2
1000	REMOVE DECALS REPAIR PAINTING <50%	5.0*
1000	FIT DECALS REPAIR PAINTING <50%	5.0*
1000	DE NIB AND POLISH SURFACE PAINT	9.0*

**JOBLING ACCIDENT REPAIR CENTRE LTD
SUNDERLAND STREET
SUNDERLAND
SR1 1UZ**

**Tel: 0191 5657291
Fax: 0191 5101683**

**Assessment Number: AJB14044
Version: connexus/2**

**Bodyshop Full Estimate Report
Printed: 06/07/2026**

PREPARATION FOR PRE-PAINTING

38.0

**Total Work Units
Total Paintwork Labour**

**129.8
13.0 HRS. £830.72**

MATERIAL COST - PAINT

COST

Total Paint Cost	£888.01
Sundry Paint Material	£120.16
Pre-Painting Sundry Materials	£137.60
Total Excluding Pearlescent Uplift	£1,145.77
Pearlescent Uplift @ 1.5%	£17.19
Total Paint And Material Cost	£1,162.96

PARTS

Price Valid: 01/06/2026

Guide No.	Description	Part Number	Bet.	Held Date	Price
2616	R/R UPP BUMPER BRKT	SEE GUIDE NO. 2620	0%		£0.00
2617	RR BUMPER BRKT SET	16 737 357 80	0%		£44.00
2620	RR BUMPER BRKT SET	16 497 979 80	0%		£46.06
3630	R/R WING BADGE	98 542 345 TC	0%		£43.73
1000	O/S/R TYRE	205/45R17	0%		£191.82 *
1000	PANEL REPAIR	SUNDRIES	0%		£21.00 *
1000	DECALS	Renew	0%		£125.74 *

Sub Total	£472.35
Sundry Parts	(3.5 %)
Total Parts	£16.53
	£488.88

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER