

Collision Engineers Ltd
77-79 Hoylake Road
Moreton
Wirral
CH49 6LH

Our Ref: SCL//48044/1

Date: 27 August 2026

Dear Sirs

Our Client: Mrs Elva Vilar
Our Client's Vehicle: VAUXHALL COMBO LIFE SE TURBO D S/S
Registration: MT21ZF
Date of Accident: 25 August 2026

AUDIT REPORT NOTIFICATION

CLIENT DETAILS

Mrs Elva Vilar
1 Tintagel Walk
Bedford
MK41 8ND

Vehicle Details

Client's Vehicle: VAUXHALL COMBO
LIFE SE TURBO D S/S
Vehicle Registration: MT21ZF
Accident Date: 25/08/2026

Home Tel: 07450220161
Work Tel:
Mobile: 07450220161

REPAIRER DETAILS

Tel:
Fax:
Email:
Engineer to Estimate Unknown

Please can you prepare an audit report based on the attached engineers report.

Damage Area – Rear Nearside: Moderate-Scratches and dents to the door, with paintwork removed.

Damage underneath the door and underneath the vehicle.

Tyre is misaligned.

Pre-existing Damage: None

TP Vehicle:

TP Registration:

TP Representative Name: Covea

If you need any further information please contact us on 0800 093 0982 selecting option 2.

Yours faithfully