

Collision Engineers Ltd
77-79 Hoylake Road
Moreton
Wirral
CH49 6LH

Our Ref: CJH/14260/1

Date: 24 August 2022

Dear Sirs

Our Client: Mr Stewart Blackburn
Our Client's Vehicle: FORD S-MAX TITANIUM TDCI 138
Registration: EU63 OZA
Date of Accident: 12 August 2022

ENGINEER NOTIFICATION

CLIENT DETAILS

Mr Stewart Blackburn
83 Lattice Avenue
Ipswich
IP4 5LN

Vehicle Details

Client's Vehicle: FORD S-MAX
TITANIUM TDCI 138
Vehicle Registration: EU63 OZA
Accident Date: 12/08/2022

Home Tel: 07961266875
Work Tel:
Mobile: 07961266875

REPAIRER DETAILS

Chaplane Accident Repair Centre Ltd
45 Brunel Way
Severalls Industrial Park
Colchester
CO4 9QX
Tel: 01206 853322
Fax:
Email: office@chaplane.co.uk
Engineer to Estimate Unknown

We would be obliged if you could contact the repairing garage and/or the client as appropriate and agree figures with the repairer – **do not authorise repairs**. Please do not agree a contract repair in excess of 80% of the vehicle value. All contract repairs must be fully itemised.

Please confirm if the vehicle is un-roadworthy and/or illegal to drive.

Vehicle Status – Undriveable

Please could you check the damage for consistency with the following accident circumstances?

Our client was stationary in traffic in the second lane on London Road in Ipswich, which has three lanes and is traffic light controlled. Your insured, to the left of our client, was proceeding in the left lane only and as your insured turned left around the bend, the rear offside of your insured's vehicle has collided with the nearside wing mirror of our client's vehicle. Your insured stopped further up the road and exchanged details.

Damage Area – Nearside: Moderate - Wing mirror smashed off and i hanging on by wires

TP Vehicle: MAN

TP Registration: M60CHT

TP Representative Name: N F U Mutual Insurance Society Ltd

If you need any further information please contact us on 0800 093 0982 selecting option 2.

Yours faithfully

QDOS Assistance

QDOS Assistance