

Our Ref:

Your Ref: EHR96041

Page 1



Audalimage MAR15131-10.jpg



Audalimage MAR15131-2.jpg



Audalimage MAR15131-9.jpg



Audalimage MAR15131-1.jpg



Audalimage MAR15131-3.jpg



Audalimage MAR15131-12.jpg

Our Ref:

Your Ref: EHR96041

Page 2



Audalimage MAR15131-8.jpg



Audalimage MAR15131-5.jpg



Audalimage MAR15131-6.jpg



Audalimage MAR15131-7.jpg



Audalimage MAR15131-11.jpg



Audalimage MAR15131-4.jpg



Our Ref:

Your Ref: EHR96041

Page 3



Audalimage MAR15131-48.jpg



Audalimage MAR15131-43.jpg




Audalimage MAR15131-44.jpg



Audalimage MAR15131-42.jpg



Audalimage MAR15131-49.jpg



Audalimage MAR15131-40.jpg


Our Ref:

Your Ref: EHR96041


Page 4



Audalimage MAR15131-41.jpg




Audalimage MAR15131-15.jpg



Audalimage MAR15131-31.jpg



Audalimage MAR15131-32.jpg



Audalimage MAR15131-33.jpg




Audalimage MAR15131-34.jpg




Our Ref:

Your Ref: EHR96041

Page 5



Audalimage MAR15131-16.jpg



Audalimage MAR15131-24.jpg



Audalimage MAR15131-22.jpg




Audalimage MAR15131-23.jpg




Audalimage MAR15131-35.jpg




Audalimage MAR15131-36.jpg




AudalImage MAR15131-37.jpg




AudalImage MAR15131-38.jpg




AudalImage MAR15131-28.jpg



AudalImage MAR15131-27.jpg



AudalImage MAR15131-26.jpg




AudalImage MAR15131-14.jpg

2.B163002 Predictive Route Data - Signal Malfunction Passive/Sporadic

The following systems are OK:

- 1.01 Engine Electronics
- 2.02 Transmission Electronics
- 3.03 Brake Electronics
- 4.09 Electronic Central Electric
- 5.15 Airbag
- 6.16 Steering Column Electronics Systems
- 7.17 Instrument Cluster
- 8.22 All-Wheel Drive Electronics
- 9.29 Left Light Control
- 10.2B Steering Column Lock
- 11.39 Right Light Control
- 12.42 Driver's Door Electronics
- 13.44 Power Steering
- 14.52 Passenger's Door Electronics
- 15.6D Rear Lid Electronics
- 16.81 Shift Lever
- 17.A5 Front Sensor For Drivers Assistant Systems
- 18.BB Rear Drivers Side Door Electronics
- 19.BC Rear Passenger Side Door Electronics
- 20.D6 Light Control Left 2
- 21.D7 Light Control Right 2






Audalimage MAR15131-17.jpg




Audalimage MAR15131-18.jpg



Audalimage MAR15131-25.jpg



Audalimage MAR15131-39.jpg



Audalimage MAR15131-53.jpg



Audalimage MAR15131-30.jpg

Our Ref:

Your Ref: EHR96041


Page 8




Audalimage MAR15131-19.jpg



Audalimage MAR15131-20.jpg




Audalimage MAR15131-21.jpg



Audalimage MAR15131-29.jpg



Audalimage MAR15131-52.jpg



Audalimage MAR15131-51.jpg




Our Ref:


Your Ref: EHR96041



AudalImage MAR15131-45.jpg



AudalImage MAR15131-46.jpg



AudalImage MAR15131-47.jpg



AudalImage MAR15131-50.jpg

SOLERA

Audatex

Pre-Repair

Vehicle Health Check Results

Vehicle Information

License #KV68NRF

Make:Audi

VIN:WAUJZZZFV02128191

Odometer:38180 miles

Vehicle Software Version:V29.20

Diagnostic Application Version:V6.01.020

Diagnostic path:Status Report

Repair Shop

Shop Name:Miles Better Vehicle Solutions Ltd

Address:Unit 1 The old Works Forsyth Road Woking Sheerwater United Kingdom

Zip Code:GU21 5SB

Telephone:01483 757788

Email:

SN:389346026853

Test Time:2026-02-11 14:06:35

Technician Name:Daniel Pulguinhas

System fault code [Pre-Repair]

The following systems is abnormal:

08 Climate Control Module

DTC (2)

1.8261000 No Basic Setting

2.811A007 Fresh Air Door Motor - Mechanical Malfunction

19 Data Bus OBD Interface

DTC (1)

1.8191604 Backup Battery - Faulty

46 Comfort System Central Control Module

DTC (3)

1.8148201 Tank Flap Locking Activation - Electrical Error

2.8126301 Tank Lid Unlock Activation - Electrical Error

3.8132C15 Right Brake/Tail Lamp Bulb - Open Circuit/Short Circuit To B+

5F Information Electronics 1

DTC (2)

1.8156401 Antenna For Telephone Mount - Electrical Error

AudalImage MAR15131-13.jpg




MAR15131-10.jpg

Our Ref:

Your Ref: EHR96041


Page 10



MAR15131-2.jpg



MAR15131-9.jpg



MAR15131-1.jpg



MAR15131-3.jpg



MAR15131-12.jpg



MAR15131-8.jpg




Our Ref:

Your Ref: EHR96041

Page 11



MAR15131-5.jpg



MAR15131-6.jpg



MAR15131-7.jpg



MAR15131-11.jpg



MAR15131-4.jpg