





## EXCAVATOR EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4539-65

Date of inspection: 08/may/2026

|          | DESCRIPTION                                 | CONDITION OR REMARKS                                                                                                                                          |
|----------|---------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>0</b> | <b>GENERAL DESCRIPTION OF THE EQUIPMENT</b> |                                                                                                                                                               |
| 0.0      | Description: Excavator Equipment            | <b>EXCAVATOR EQUIPMENT</b><br><b>Manufacturer: HITACHI</b><br><b>MODEL: ZX200-B5</b><br><b>REG NO: A 6643-Dhi qar</b><br><b>CHASSIS NO: HCMDCKA0E00305130</b> |
| <b>1</b> | <b>SECTION</b>                              |                                                                                                                                                               |
| 1.1      | Manufacturers operation manual              | N/A                                                                                                                                                           |
| 1.2      | Operator competency certificate             | OK                                                                                                                                                            |
| 1.3      | Hand Brake Interlock                        | OK                                                                                                                                                            |
| 1.4      | Hydraulic oil level                         | OK                                                                                                                                                            |
| 1.5      | Condition of oil                            | OK                                                                                                                                                            |
| 1.6      | System and hoses                            | OK                                                                                                                                                            |
| 1.7      | Lubrication                                 | OK                                                                                                                                                            |
| 1.8      | Engine Indication                           | OK                                                                                                                                                            |
| 1.9      | Boom structure                              | OK                                                                                                                                                            |
| 1.10     | Control levers                              | OK                                                                                                                                                            |
| 1.11     | Track Roller frame                          | OK                                                                                                                                                            |
| 1.12     | Wear , damage , cracks , leaks              | OK                                                                                                                                                            |
| 1.13     | Bucket                                      | OK                                                                                                                                                            |
| 1.14     | Pins , Grease lines                         | OK                                                                                                                                                            |
| 1.15     | Tracks/ Tyres / Crawler                     | OK                                                                                                                                                            |
| 1.16     | Windows / Mirrors / Lights                  | OK                                                                                                                                                            |
| 1.17     | Undercarriage (including leaks)             | OK                                                                                                                                                            |
| 1.18     | Belts / Hoses / Bolts                       | OK                                                                                                                                                            |
| 1.19     | Electrical System                           | OK                                                                                                                                                            |
| 1.20     | Power Train                                 | OK                                                                                                                                                            |
| 1.21     | Power Unit                                  | OK                                                                                                                                                            |
| 1.22     | Power Link                                  | OK                                                                                                                                                            |
| 1.23     | Motion Alarm                                | OK                                                                                                                                                            |
| 1.24     | Counter Weight                              | OK                                                                                                                                                            |
| 1.25     | Main Frame                                  | OK                                                                                                                                                            |
| 1.26     | Fire Extinguisher                           | OK                                                                                                                                                            |
| 1.27     | First Aid                                   | OK                                                                                                                                                            |





## EXCAVATOR EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4539-65

Date of inspection: 08/may/2026

Comment:



Surveyor's Name: Mohamed Abdel Halim

Signature



## Certificate of Thorough Examination & NDE for Hydraulic Excavator

|                                                                 |                                |
|-----------------------------------------------------------------|--------------------------------|
| Date of Through Examination: 08/may/2026                        | Certificate number: ST-4539-65 |
| Name and Address of employer: MSK Co., BASRA , IRAQ             |                                |
| Address of premises at which the examination was made: MSK YARD |                                |

| Identification NO | QTY | Description                                                                                                                                                                                                                                                 | Date of next exam |
|-------------------|-----|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|
| HCMDCKA0E00305130 | 1   | <b>EXCAVATOR EQUIPMENT</b><br><br><b>MANUFACTURER: HITACHI</b><br><b>MODEL: ZX200-B5</b><br><b>REG NO: A 6643-Dhi qar</b><br><b>CHASSIS NO: HCMDCKA0E00305130</b><br><b>BUCKET S/N: 02</b><br><br><b>EXAMINED IN ACCORDING TO BS EN 474 -5:2006+A3:2013</b> | 07/may/2027       |

| Tools Details                 |                                 |
|-------------------------------|---------------------------------|
| Measuring Tape S/N: SCP-L-001 | Vernier Calliper S/N: SCP-L-002 |

| NDT Details                                                                                                       |                                 |                       |
|-------------------------------------------------------------------------------------------------------------------|---------------------------------|-----------------------|
| Standard: BS EN ISO 9934-1                                                                                        | Equipment type: YOKE S\N: 3291K | Contrast Media: WHITE |
| Procedure: SPS-IMS-P027                                                                                           | Method: WET                     | Indicator: MAG INK    |
| <b>Result</b> MPI was carried out on the critical stress areas of bucket were found free from any surface defects |                                 |                       |

|                                                                                         |     |  |    |   | Was the examination carried out:                   |     |   |    |   |
|-----------------------------------------------------------------------------------------|-----|--|----|---|----------------------------------------------------|-----|---|----|---|
| Is this the first examination after installation or assembly at a new site or location? | YES |  | NO | ✓ | Within an interval of 6 months?                    | YES |   | NO | ✓ |
|                                                                                         |     |  |    |   | Within an interval of 12 months?                   | YES | ✓ | NO |   |
| If the answer to the above question is YES, has the equipment been installed correctly? | YES |  | NO |   | In accordance with an examination scheme?          | YES | ✓ | NO |   |
|                                                                                         |     |  |    |   | After the occurrence of exceptional circumstances? | YES |   | NO | ✓ |

|                                                                                  |
|----------------------------------------------------------------------------------|
| Identification of any part found to have a defect: (NONE)                        |
| Particulars of any repair, renewal or alteration required: (NONE)                |
| Particulars of any tests carried out: (Visual, Function, Performance, MPI Tests) |

|                                    |     |   |    |  |
|------------------------------------|-----|---|----|--|
| Is This Equipment Safe To Operate? | YES | ✓ | NO |  |
|------------------------------------|-----|---|----|--|

Name of person making this report:  
 Mohamed Abdel Halim

Signature:



Name of person authenticating this report:  
 Mostafa Shama

Signature:



Name of employer of persons making and authenticating this report:  
 Scope petroleum services: lifting@scopeps.com