




EXCAVATOR EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4536-25

Date of inspection: 05/march/2023

0	GENERAL DESCRIPTION OF THE EQUIPMENT	
0.0	Description: Excavator Equipment	EXCAVATOR EQUIPMENT Manufacturer: HITACHI MODEL: ZX200 REG NO: A 26286-Basra CHASSIS NO: HCM1G600P00117888
1	SECTION	CONDITION
1.1	Manufacturers operation manual	N/A
1.2	Operator competency certificate	OK
1.3	Hand Brake Interlock	OK
1.4	Hydraulic oil level	OK
1.5	Condition of oil	OK
1.6	System and hoses	OK
1.7	Lubrication	OK
1.8	Engine Indication	OK
1.9	Boom structure	OK
1.10	Control levers	OK
1.11	Track Roller frame	OK
1.12	Wear , damage , cracks , leaks	OK
1.13	Bucket	OK
1.14	Pins , Grease lines	OK
1.15	Tracks/ Tyres / Crawler	OK
1.16	Windows / Mirrors / Lights	OK
1.17	Undercarriage (including leaks)	OK
1.18	Belts / Hoses / Bolts	OK
1.19	Electrical System	OK
1.20	Power Train	OK
1.21	Power Unit	OK
1.22	Power Link	OK
1.23	Motion Alarm	OK
1.24	Counter Weight	OK
1.25	Main Frame	OK
1.26	Fire Extinguisher	OK
1.27	First Aid	OK





EXCAVATOR EQUIPMENT INSPECTION CHECK LIST

Comment:



Surveyor's Name: Mohamed Abdel Halim

Signature



Certificate of Thorough Examination & NDE for Hydraulic Excavator

Date of Thorough Examination: 05/march/2023	Certificate number: ST-4536-25
Name and Address of employer: MSK Co., BASRA , IRAQ	
Address of premises at which the examination was made: MSK YARD	

Identification NO	QTY	Description	Date of next exam
HCM1G600P00117888	1	EXCAVATOR EQUIPMENT MANUFACTURER: HITACHI MODEL: ZX200 REG NO: A 26286-Basra CHASSIS NO: HCM1G600P00117888 BUCKET S/N: 02 EXAMINED IN ACCORDING TO BS EN 474 -5:2006+A3:2013	04/March/2024

Tools Details	
Measuring Tape S/N: SCP-L-001	Vernier Calliper S/N: SCP-L-002

NDT Details			
Standard: BS EN ISO 9934-1	Equip type: YOKE S/N: 3291K	Media: WHITE	Indicator: MAG INK
Procedure: SPS-IMS-P027	Method: WET		
Result: MPI was carried out on the critical stress areas of bucket - found free from any surface defects.			

Was the examination carried out:			
Is this the first examination after installation?	YES ☒ NO ☐	Within an interval of 6 months?	YES ☒ NO ☐
Has the equipment been installed correctly?	YES ☒ NO ☐	Within an interval of 12 months?	YES ☒ NO ☐

Identification of any part found to have a defect: (NONE)
Particulars of any repair, renewal or alteration required: (NONE)
Particulars of any tests carried out: (Visual, Function, Performance, MPI Tests)

Is This Equipment Safe To Operate? YES ☒ NO ☐

Name of person making report:
Mohamed Abdel Halim

Signature: _____



Name of person authenticating report:
Mostafa Shama

Signature: _____

