



Certificate of Thorough Examination & NDE for Hydraulic Excavator

Date of Thorough Examination: 11/may/2026			Certificate number: ST-4539-79
Name and Address of employer for whom the thorough examination was made: MSK Co., BASRA , IRAQ			Address of premises at which the examination was made: MSK YARD
Identification NO	QTY	Description	Date of next examination
HCMDCKA0P00302099	1	<u>EXCAVATOR EQUIPMENT</u> MANUFACTURER: HITACHI MODEL: ZX200 REG NO: A 6297-Basra CHASSIS NO: HCMDCKA0P00302099 BUCKET S/N: 02 EXAMINED IN ACCORDING TO BS EN 474 -5:2006+ A3:2013	10/May/2027

Tools Details

Tools Details	Measuring Tape S/N: SCP-L-001	Vernier Calliper S/N: SCP-L-002
---------------	-------------------------------	---------------------------------

NDT Details

Standard: BS EN ISO 9934-1	Equipment type: YOKE SN: 3291K	Contrast Media: WHITE							
Procedure: SPS-IMS-P027	Method: WET	Indicator: MAG INK							
Result	MPI was carried out on the critical stress areas of bucket were found free from any surface defects								
Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out:				
					Within an interval of 6 months?	YES		NO	✓
If the answer to the above question is YES, has the equipment been installed correctly?					Within an interval of 12 months?	YES	✓	NO	
	YES		NO		In accordance with an examination scheme?	YES	✓	NO	
					After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (None)			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: (NONE)			
Particulars of any tests carried out as part of the examination: (Visual , Function , Performance , MPI Tests)			
Is This Equipment Safe To Operate?	YES	✓	NO

Name of person making this report: Mohamed Abdel Hameed	Name of person authenticating this report: Mostafa Shama
Signature:	
Name of employer of persons making and authenticating this report:	
Scope petroleum services: lifting@scopeps.com	

Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan
 Contacts: operation@scopeps.com / sales@scopeps.com
 Phone: +964 7803222202 / +964 7803773775



EXCAVATOR EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4539-79

Date of inspection: 11/May/2026

Comment:



Surveyor's Name: Mohamed Abdel Halim

Signature



Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan
Contacts: operation@scopeps.com/sales@scopeps.com
Phone: +964 7803222202 / +964 7803773775



EXCAVATOR EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4539-79

Date of inspection: 11/may/2026

	DESCRIPTION	CONDITION OR REMARKS
0	GENERAL DESCRIPTION OF THE EQUIPMENT	
0.0	Description: Excavator Equipment	EXCAVATOR EQUIPMENT Manufacturer: HITACHI MODEL: ZX200 REG NO: A 6297-Basra CHASSIS NO: HCMDCKA0P00302099
1	SECTION	
1.1	Manufacturers operation manual	N/A
1.2	Operator competency certificate	OK
1.3	Hand Brake Interlock	OK
1.4	Hydraulic oil level	OK
1.5	Condition of oil	OK
1.6	System and hoses	OK
1.7	Lubrication	OK
1.8	Engine Indication	OK
1.9	Boom structure	OK
1.10	Control levers	OK
1.11	Track Roller frame	OK
1.12	Wear , damage , cracks , leaks	OK
1.13	Bucket	OK
1.14	Pins , Grease lines	OK
1.15	Tracks/ Tyres / Crawler	OK
1.16	Windows / Mirrors / Lights	OK
1.17	Undercarriage (including leaks)	OK
1.18	Belts / Hoses / Bolts	OK
1.19	Electrical System	OK
1.20	Power Train	OK
1.21	Power Unit	OK
1.22	Power Link	OK
1.23	Motion Alarm	OK
1.24	Counter Weight	OK
1.25	Main Frame	OK
1.26	Fire Extinguisher	OK
1.27	First Aid	OK



Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan
 Contacts: operation@scopeps.com/sales@scopeps.com
 Phone: +964 7803222202 / +964 7803773775