




MOTOR GRADER EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4539-45

Date of inspection: 15 / November / 2025

	DESCRIPTION	CONDITION OR REMARKS
0	GENERAL DESCRIPTION OF THE EQUIPMENT	
0.0	Description: Motor Grader Equipment	<u>MOTOR GRADER EQUIPMENT</u> Manufacturer: CATERPILLAR MODEL: 12G REG NO: 14 A 9408 CHASSIS NO: 61M11232
1	SECTION	
1.1	Manufacturers operation manual	N/A
1.2	Operator competency certificate	OK
1.3	Hand Brake Interlock	OK
1.4	Hydraulic oil level	OK
1.5	Condition of oil	OK
1.6	System and hoses	OK
1.7	Lubrication	OK
1.8	Engine Indication	OK
1.9	Boom structure	OK
1.10	Control levers	OK
1.11	Track Roller frame	OK
1.12	Wear , damage , cracks , leaks	OK
1.13	Bucket	OK
1.14	Pins , Grease lines	OK
1.15	Tracks/ Tyres / Crawler	OK
1.16	Windows / Mirrors / Lights	OK
1.17	Undercarriage (including leaks)	OK
1.18	Belts / Hoses / Bolts	OK
1.19	Electrical System	OK
1.20	Power Train	OK
1.21	Power Unit	OK
1.22	Power Link	OK
1.23	Motion Alarm	OK
1.24	Counter Weight	OK
1.25	Main Frame	OK
1.26	Fire Extinguisher	OK
1.27	First Aid	OK





MOTOR GRADER EQUIPMENT INSPECTION CHECK LIST

Annex to certificate N°: ST-4539-45

Date of inspection: 15 / November / 2025

Comment:



Surveyor's Name: Mohamed Abdel Halim

Signature



Address: Burjesia-Tuba Area -After the Bridge Hamoud El-Wabdan

Contacts: operation@scopeps.com/sales@scopeps.com

Phone: +964 7803222202 / +964 7803773775



Certificate of Thorough Examination & NDE for Hydraulic Motor Grader

Date of Thorough Examination: 15 / November / 2025			Certificate number: ST-4539-45					
Name and Address of employer for whom the thorough examination was made: MSK Co., BASRA , IRAQ			Address of premises at which the examination was made: MSK YARD					
Identification NO	QTY	Description	Date of next examination					
61M11232	1	MOTOR GRADER EQUIPMENT MANUFACTURER: CATERPILLAR MODEL: 12G REG NO: 14 A 9408 CHASSIS NO: 61M11232 EXAMINED IN ACCORDING TO BS EN 474 -5:2006+ A3:2013	14 / November / 2026					
Tools Details								
Tools Details		Measuring Tape S/N: SCP-L-001	Vernier Calliper S/N: SCP-L-002					
NDT Details								
Standard: BS EN ISO 9934-1		Equipment type: YOKE S/N: 3291K		Contrast Media: WHITE				
Procedure: SPS-IMS-P027		Method: WET		Indicator: MAG INK				
Result	MPI was carried out on the critical stress areas of bucket were found free from any surface defects							
Is this the first examination after installation or assembly at a new site or location?	YES		NO	✓	Was the examination carried out:			
					Within an interval of 6 months?			
If the answer to the above question is YES, has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?			
					YES	✓	NO	
				In accordance with an examination scheme?	YES	✓	NO	
				After the occurrence of exceptional circumstances?	YES		NO	✓
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (None)								
Particulars of any repair, renewal or alteration required to remedy the defect identified above: (NONE)								
Particulars of any tests carried out as part of the examination: (Visual , Function , Performance , MPI Tests)								
Is This Equipment Safe To Operate?								
YES								
✓								
NO								
Name of person making this report: Mohamed Abdel Halim			Name of person authenticating this report: Mostafa Shama					
Signature: 								
Name of employer of persons making and authenticating this report: Scope petroleum services: lifting@scopeps.com								