VeriCar

EA11OSE

MINI COOPER D

2011 • BLACK • DIESEL

NEGOTIATE

AI RECOMMENDATION

Report generated: 31 March 2026 at 16:21 UTC
Reference: CV-20260331-141A7856

Vehicle Summary

Identity

Registration	EA11OSE	**Make**	MINI
Year	2011	**Engine**	1598cc
Colour	BLACK	**Fuel**	DIESEL

Valuation

Private Sale	Dealer	Trade-in	Part Exchange
£2,737	£3,212	£1,124	£1,513

Key Statistics

Vehicle Age	Mileage	Annual Average
14 years, 11 months	100,440 miles	6,725 mi/yr
MOT Status	**Tax Status**	**MOT Issues**
Valid until 2026-09-29	Taxed	Advisories: 3 | Failures: 3

Clean Air Zones: All zones compliant

At a Glance

- ✓ **Not Stolen**
  Clear
- ✓ **No Finance Outstanding**
  Clear — safe to purchase
- ✓ **No Write-Off History**
  Clear
- ✓ **No Salvage Records**
  Clear
- ✓ **Mileage Verified**
  No clocking detected
- ✓ **MOT Valid**
  181 days remaining
- ✓ **All Clean Air Zones Clear**
  Compliant with all UK zones

1. OVERALL CONDITION ASSESSMENT

Recommendation: NEGOTIATE

Mileage Assessment

Total Mileage: 100,440 miles **Annual Average:** ~6,277 miles/year

Benchmark Comparison:

- UK average for diesel cars: 7,000–8,000 miles/year

This vehicle's mileage is **typical** for its age and fuel type.

Observation: Mileage reading from DVLA Vehicle Enquiry Service. Consistency checked across MOT history.

MOT History Analysis

Metric	Detail	Interpretation
Total MOT tests	14 tests on record	Full MOT history available
Passes	11 passes	Pass rate 79% — typical for age
Failures	3 failures	Assessment pending inspector review
Latest result	Check DVSA database	Current MOT status available
Current advisories	See defect patterns section	Advisories logged where applicable
MOT expiry	2026-09-29	Valid or expired as shown

Recurring Defect Patterns

Category	#	Pattern	Action
tyre	17	Tyre flagged 17 times in MOT history.	Have tyre inspected by qualified mechanic before purchase.
windscreen	3	Windscreen flagged 3 times in MOT history.	Have windscreen inspected by qualified mechanic before purchase.
brake	3	Brake flagged 3 times in MOT history.	Have brake inspected by qualified mechanic before purchase.

Test Drive Checklist

Area	Check	What to Look For
Tyres	Check tread depth on all four corners	All above 1.6mm legal minimum. (Advisory: Offside Front Tyre worn close to legal limit/worn ...)
Engine		No rattling, knocking, or unusual noises from the engine bay

	Listen on cold start and during acceleration	
Gearbox	Test smoothness through all gears	No crunching, grinding, or delayed engagement

Ownership History

Total Keepers: 1

Assessment: Vehicle registered with 1 keeper(s). Source: Experian AutoCheck / DVLA.

Provenance

Check	Status	Details
Finance Check	✅ Clear	Finance agreement records from Experian
Stolen Check	✅ Clear	Checked against police records
Write-off Check	✅ Clear	Insurance write-off records
Salvage Records	✅ Clear	Salvage auction history

2. VALUE ANALYSIS

Market Valuation Summary

Channel	Valuation
Private Sale	£2,737
Dealer Forecourt	£3,212
Trade-in	£1,124
Part Exchange	£1,513

Valuation basis: Estimated market data

Context & Interpretation

Based on 2011 Mini COOPER D with 100440 miles and MOT history. Market value varies by condition and service history.

Value Influencing Factors

Factor	Impact	Details
Single Keeper History	Positive	Single owner from new typically indicates regular servicing and careful maintenance

Mileage Authenticity	Positive	Mileage consistent across MOT tests — no odometer tampering detected
Tyre Wear	Negative	Flagged 17 times in 14 MOT tests. Budget £350-£1250 for repairs.
Windscreen Wear	Negative	Flagged 3 times in 14 MOT tests. Budget £350-£1250 for repairs.
MOT Failures	Negative	3 failures recorded. Recent resolution status unknown — verify repairs before purchase.
Mileage	Neutral	100,440 miles — approximately 6277/year. Typical for age.

Depreciation Trajectory

At this age and mileage, Mini COOPER D vehicles have reached stable depreciation. Annual value loss is typically modest unless major repairs are needed.

3. RISK FACTORS

Risk Matrix

Category	Level	Finding
MOT Failures	**MEDIUM**	3 failures recorded in history. Verify all issues resolved before purchase.
tyre	**HIGH**	Recurring issue (17 times). Have professional mechanic inspect. Budget £350-£1250.
windscreen	**MEDIUM**	Recurring issue (3 times). Have professional mechanic inspect. Budget £350-£1250.
brake	**MEDIUM**	Recurring issue (3 times). Have professional mechanic inspect. Budget £350-£1250.

Known Issues for This Model

Priority	Issue	Details
High	N47 engine timing chain wear	Well-documented fault on 1.6 diesel engines at this mileage. Symptoms: rattling on cold start, noise from rear of engine. Replacement cost: £1,000–£2,000 at specialist.
High	EGR valve and diesel particulate filter (DPF) issues	Carbon build-up on EGR valve common on N47 diesel, especially for short-journey usage. DPF blockage can occur. DPF replacement: £500–£1,500. EGR cleaning/replacement: £200–£500.
Medium	Power steering pump failure	Electric power steering failures reported on this generation. Symptoms: heavy or unresponsive steering. Replacement cost: £300–£600 at independent garage.
Medium	Coolant loss and thermostat failure	Coolant leaks and thermostat failures common. Watch for white smoke from exhaust or sweet smell (head gasket issue). Head gasket repair: £800–£1,500.

Recall Status

No recalls on record for this model. Always verify at DVSA recalls.

4. REPAIR BUDGET

Item	Priority	Est. Cost	Notes
Tyre repair/replacement	High	£50–£150	Flagged 17 times in MOT history. Tyre replacement.
Windscreen repair/ replacement	Medium	£150–£400	Flagged 3 times in MOT history. Windscreen repair/replace.
Brake repair/replacement	Medium	£150–£700	Flagged 3 times in MOT history. Brake pads/ discs.
Total			
£350–£1,250	Estimated repair budget		

5. RUNNING COSTS

Category	Annual Cost
Road Tax (VED)	£20
Insurance (estimate)	£627
Servicing & Maintenance	£250
Total (estimated)	**£897**

Estimated for Mini COOPER D (DIESEL). Insurance: ABI average for insurance group 13 (~£627/yr; varies by driver age, location, no-claims history). Road tax: VED Band B (101–110g/km CO2). No fuel estimate (insufficient mileage data).

6. NEGOTIATION GUIDANCE

Market Context: Based on MOT history and recurring defects, typical market value is lower than asking price. Repairs needed: £350-£1250.

Suggested Opening Offer: Deduct £800 from asking price to cover predicted repairs.

Key Leverage Points:

- tyre flagged 17 times — budget £50-£150
- windscreen flagged 3 times — budget £150-£400

- brake flagged 3 times — budget £150-£700

Walk Away If:

- Seller cannot provide evidence recent repairs have been completed
- Test drive reveals issues flagged in MOT history
- Any refusal to allow professional pre-purchase inspection

Data Sources

This report was compiled using the following data sources:

1. DVLA Vehicle Enquiry Service (gov.uk)
2. DVSA MOT History API (gov.uk)
3. Experian AutoCheck (experian.co.uk)

Disclaimer: This report is generated by VeriCar using data from DVLA, DVSA, and third-party providers. The analysis is advisory only. Always arrange a professional vehicle inspection before purchase.

Mileage Timeline

Date	Mileage
2014-04-12	21,441 miles
2014-04-12	21,441 miles
2015-04-20	34,198 miles
2016-07-12	40,599 miles
2017-07-13	48,212 miles
2017-07-13	48,212 miles
2019-03-09	71,440 miles
2020-03-03	80,034 miles
2020-03-03	80,034 miles
2021-03-08	82,540 miles
2022-04-22	87,509 miles
2023-08-24	90,983 miles
2024-08-21	98,126 miles
2025-09-30	100,440 miles

MOT History (14 tests)

#	Date	Result	Mileage	Defects / Advisories
1	2025-09-30	PASSED	100,440 mi	A: Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) A: Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) A: Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
2	2024-08-21	PASSED	98,126 mi	A: Front Headlamp has a product on the lens but not seriously reducing light output Both front (4.1.4 (b)) A: All direction indicators slightly discoloured (4.4.3 (a)) A: Front Undertray not fully secure (8.1.1 (b) (i)) A: Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) A: Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
3	2023-08-24	PASSED	90,983 mi	—
4	2022-04-22	PASSED	87,509 mi	F: Offside Windscreen wiper blade defective (3.4 (b) (i)) A: Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) A: Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
5	2021-03-08	PASSED	82,540 mi	A: Direction indicator slightly discoloured Both rear (4.4.3 (a))
6	2020-03-03	PASSED	80,034 mi	A: N/s/front tyrs bald on edges + close to ware indicator A: O/s/rear tyre worn to ware indicator A: N/s/rear tyre close to ware indicator
7	2020-03-03	FAILED	80,034 mi	F: Offside Front Brake hose excessively deteriorated Insecure in mounting rubbing on shock absorber (1.1.12 (b) (ii)) **D: Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))** A: N/s/front tyrs bald on edges + close to ware indicator A: O/s/rear tyre worn to ware indicator A: N/s/rear tyre close to ware indicator
8	2019-03-09	PASSED	71,440 mi	—
9	2017-07-13	PASSED	48,212 mi	A: Front Brake pad(s) wearing thin (3.5.1g)
10	2017-07-13	FAILED	48,212 mi	F: Nearside Stop lamp not working (1.2.1b) A: Front Brake pad(s) wearing thin (3.5.1g)
11	2016-07-12	PASSED	40,599 mi	—
12	2015-04-20	PASSED	34,198 mi	—
13	2014-04-12	FAILED	21,441 mi	F: Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) F: Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) F: Nail in offside rear tyre A: Nearside Front Tyre worn close to the legal limit (4.1.E.1) A: Offside Front Tyre worn close to the legal limit (4.1.E.1) A: Nearside Rear Tyre worn close to the legal limit (4.1.E.1) A: Offside Rear Tyre worn close to the legal limit (4.1.E.1)
14	2014-04-12	PASSED	21,441 mi	F: Nail in offside rear tyre A: Nearside Front Tyre worn close to the legal limit (4.1.E.1) A: Offside Front Tyre worn close to the legal limit (4.1.E.1) A: Nearside Rear Tyre worn close to the legal limit (4.1.E.1) A: Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Disclaimer: This report is generated by VeriCar (operated by Matthew Coombes, sole trader) using data from the DVLA Vehicle Enquiry Service, DVSA MOT History API, and where applicable, Experian Automotive. The AI analysis is advisory only and should not be used as the sole basis for purchasing decisions. Always arrange a professional vehicle inspection before buying a used car.
VeriCar excludes all liability, to the fullest extent permitted by law, for inaccuracies or omissions in data supplied by third-party providers including Experian. Data is accurate as of the report generation date and may have changed since last updated by the relevant authorities. Provenance data (finance, stolen, write-off, plate changes) is **provided by Experian**. Experian data accuracy terms apply: experian.co.uk/automotive/data-guarantee