




Quality Assurance Management, Inc.
1620 Valwood Pkwy, Ste. 128
Carrollton, TX 75006
972-331-5800
QAM.com

Oxygen Test Report




Client:	TEST CLIENT	Analyzer:	Delta F
Facility:	QAM HQ	Serial Number:	PT-18690-V6
Tool / Equipment ID:	TEST123	Calibration Due:	7/2021
System:	PN2	Instrument Flow:	2.0 SCFH
Source ID:	SRC-TST-ID	Start Time/Date:	12:48 02/26/21
Test Point ID:	PN2 LINE	Stop Time/Date:	13:11 02/26/21
Test Gas:	Nitrogen	Test Duration:	22 minutes 43 seconds
Test Flow:	4.3 SCFH	Average:	0.0 PPB
Technician:	JCH	Final:	0.0 PPB
		Specification:	20 PPB

Comments: TESTING THE SAVE GRAPH FUNCTION



Quality Assurance Management, Inc.
1620 Valwood Pkwy, Ste. 128
Carrollton, TX 75006
972-331-5800
QAM.com

Moisture Test Report



Client:	TEST CLIENT	Analyzer:	Tracer 2
Facility:	QAM HQ	Serial Number:	17367-44-1
Tool / Equipment ID:	TEST123	Calibration Due:	8/2021
System:	PN2	Instrument Flow:	2.3 SCFH
Source ID:	SRC-TST-ID	Start Time/Date:	12:48 02/26/21
Test Point ID:	PN2 LINE	Stop Time/Date:	13:11 02/26/21
Test Gas:	Nitrogen	Test Duration:	22 minutes 43 seconds
Test Flow:	4.3 SCFH	Average:	57.5 PPB
Technician:	JCH	Final:	57.2 PPB
		Specification:	20 PPB

Comments: TESTING THE SAVE GRAPH FUNCTION