




Quality Assurance Management, Inc.
1620 Valwood Pkwy, Ste. 128
Carrollton, TX 75006
972-331-5800
QAM.com

Oxygen Test Report




Client:	TEXAS INSTRUMENTS	Analyzer:	Delta F
Facility:	RFAB	Serial Number:	PT-18690-V6
Tool / Equipment ID:		Calibration Due:	7/2021
System:		Instrument Flow:	2.0 SCFH
Source ID:		Start Time/Date:	09:00 11/02/20
Test Point ID:		Stop Time/Date:	09:02 11/02/20
Test Gas:		Test Duration:	2 minutes 6 seconds
Test Flow:	4.3 SCFH	Average:	6.3 PPB
Technician:		Final:	6.2 PPB
		Specification:	20 PPB

Comments:



Quality Assurance Management, Inc.
1620 Valwood Pkwy, Ste. 128
Carrollton, TX 75006
972-331-5800
QAM.com

Moisture Test Report



Client:	TEXAS INSTRUMENTS	Analyzer:	Tracer 2
Facility:	RFAB	Serial Number:	17367-44-1
Tool / Equipment ID:		Calibration Due:	8/2021
System:		Instrument Flow:	2.3 SCFH
Source ID:		Start Time/Date:	09:00 11/02/20
Test Point ID:		Stop Time/Date:	09:02 11/02/20
Test Gas:		Test Duration:	2 minutes 6 seconds
Test Flow:	4.3 SCFH	Average:	0.0 PPB
Technician:		Final:	0.0 PPB
		Specification:	20 PPB

Comments: