REPORT NO. DATE MILLBROOK201506 2015-06-15 62

TOTAL APPLIANCES

TEST ENGINEER NAME

TEST DEVICE DESCRIPTION Seaward PAC1500XI TEST DEVICE SERIAL NO. U25-0572 Ian Cheesbrough

TEST ENGINEER SIGNATURE Items in order of testing.

Items in order of testing.											
APPLIANCE ID	APPLIANCE DESCRIPTION	APPLIANCE LOCATION	CLASS	VISUAL	EARTH Ohms	INSULATION MOhms	FUNCTIONAL	NEXT TEST	PASS/FAIL	COMMENTS	
LGT01	Light, table	Room 1 - Old Harry	II	OK		>20	Yes	+2yrs	PASS		
LGT02	Light, table	Room 1 - Old Harry	II	OK		>20	Yes	+2yrs	PASS		
TV_01	Television	Room 1 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	Electronic start	
KET01	Kettle	Room 1 - Old Harry	I	OK	0.044	>20	Yes	+2yrs	PASS	Fixing bolt of element accessible behind small cover in base. All-plastic construction with no visible or touchable metal parts besides element.	
DRY01	Dryer, hair	Room 1 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.	
CLK01	Clock, alarm	Room 1 - Old Harry	II	OK		>20	Yes	+2yrs	PASS		
LGT03	Light, table	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS		
LGT04	Light, table	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS		
TV_02	Television	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS	Electronic start	
KET02	Kettle	Room 3 - Durlston Room	I	OK	0.078	>20	Yes	+2yrs	PASS	Fixing bolt of element accessible behind small cover in base. All-plastic construction with no visible or touchable metal parts besides element.	
DRY02	Dryer, hair	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.	
CLK02	Clock, alarm	Room 3 - Durlston Room	II	OK		>20	Yes	+2yrs	PASS		
EXT01	Extension, fixed socket	Room 3 - Durlston Room	I	OK	0.067	>20	Yes	+2yrs	PASS		
EXT02	Extension, fixed socket	Room 3 - Durlston Room	I	OK	0.049	>20	Yes	+2yrs	PASS		
LGT05	Light, table	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS		
LGT06	Light, table	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS		
LGT07	Light, table	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS		
TV_03	Television	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS	Electronic start	
KET03	Kettle	Room 8 - Tyneham	I	OK	0.047	>20	Yes	+2yrs	PASS	Fixing bolt of element accessible behind small cover in base. All-plastic construction with no visible or touchable metal parts besides element.	
DRY03	Dryer, hair	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.	
CLK03	Clock, alarm	Room 8 - Tyneham	II	OK		>20	Yes	+2yrs	PASS		
LGT08	Light, table	Room 2 - Brownsea Island	II	OK		>20	Yes	+2yrs	PASS		
LGT09	Light, table	Room 2 - Brownsea Island	II	OK		>20	Yes	+2yrs	PASS		
TV_04	Television	Room 2 - Brownsea Island	I	OK	0.065	>20	Yes	+2yrs	PASS	Electronic start	
KET04	Kettle	Room 2 - Brownsea Island	I	OK	0.071	>20	Yes	+2yrs	PASS	Fixing bolt of element accessible behind small cover in base. All-plastic construction with no visible or touchable metal parts besides element.	
DRY04	Dryer, hair	Room 2 - Brownsea Island	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.	
CLK04	Clock, alarm	Room 2 - Brownsea Island	II	OK		>20	Yes	+2yrs	PASS		
EXT03	Extension, IEC	Room 2 - Brownsea Island	I	OK	0.049	>20	Yes	+2yrs	PASS		
LGT10	Light, table	Room 4 - Purbeck Suite	II	OK		>20	Yes	+2yrs	PASS		
LGT11	Light, table	Room 4 - Purbeck Suite	II	OK		>20	Yes	+2yrs	PASS		
TV_05	Television	Room 4 - Purbeck Suite	I	OK	0.110	>20	Yes	+2yrs	PASS	Electronic start. Worst earth rating on RCA connectors at left side.	
KET05	Kettle	Room 4 - Purbeck Suite	I	OK	0.062	>20	Yes	+2yrs	PASS	Fixing bolt of element accessible behind small cover in base. All-plastic construction with no visible or touchable metal parts besides element.	
DRY05	Dryer, hair	Room 4 - Purbeck Suite	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.	
LGT12	Light, table	Room 5 - Kimmeridge	II	OK		>20	Yes	+2yrs	PASS		
LGT13	Light, table	Room 5 - Kimmeridge	II	OK		>20	Yes	+2yrs	PASS		
TV_06	Television	Room 5 - Kimmeridge	I	OK	0.029	>20	Yes	+2yrs	PASS	Electronic start. Worst earth rating on RCA connectors at left side.	
EXT03	Extension, IEC	Room 5 - Kimmeridge	I	OK	0.052	>20	Yes	+2yrs	PASS		
KET06	Kettle	Room 5 - Kimmeridge	I	OK	0.071	>20	Yes	+2yrs	PASS	Fixing bolt of element accessible behind small cover in base. All-plastic construction with no visible or touchable metal parts besides element.	
DRY06	Dryer, hair	Room 5 - Kimmeridge	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.	
CLK06	Clock, alarm	Room 5 - Kimmeridge	II	OK		>20	Yes	+2yrs	PASS		
LGT14	Light, table	Room 6 - Lulworth Cove	II	OK		>20	Yes	+2yrs	PASS		
LGT15	Light, table	Room 6 - Lulworth Cove	II	OK		>20	Yes	+2yrs	PASS		
TV_07	Television	Room 6 - Lulworth Cove	II	OK		>20	Yes	+2yrs	PASS	Electronic start	
KET07	Kettle	Room 6 - Lulworth Cove	I	OK	0.059	>20	Yes	+2yrs	PASS	Fixing bolt of element accessible behind small cover in base. All-plastic construction with no visible or touchable metal parts besides element.	
DRY07	Dryer, hair	Room 6 - Lulworth Cove	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.	
CLK07	Clock, alarm	Room 6 - Lulworth Cove	II	OK		>20	Yes	+2yrs	PASS		
LGT16	Light, table	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs	PASS		
LGT17	Light, table	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs	PASS		
TV_08	Television	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	Electronic start	
KET08	Kettle	Room 7 - Old Harry	I	OK	0.067	>20	Yes	+2yrs	PASS	Fixing bolt of element accessible behind small cover in base. All-plastic construction with no visible or touchable metal parts besides element.	
DRY08	Dryer, hair	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs	PASS	No rating plate or info in instructions. All-plastic construction indicates Class II.	
CLK08	Clock, alarm	Room 7 - Old Harry	II	OK		>20	Yes	+2yrs	PASS		
VAC01	Cleaner, vacuum, DC33	Cleaning cupboard	II	OK		>20	Yes	+2yrs	PASS		
LGT18	Light, table	Landing	II	OK		>20	Yes	+2yrs	PASS		
LGT19	Light, table	Hall	II	OK		>20	Yes	+2yrs	PASS		
IRN01	Press, steam	Hall	I	OK	0.106	>20	Yes	+2yrs	PASS	Earth taken from metal shell. Heating plate is isolated.	
	•							,			

VAC02	Cleaner, vacuum, DC14	Downstairs	II	OK		>20	Yes	+2yrs	PASS
FAN01	Fan, floor, upright	Downstairs	II	OK		>20	Yes	+2yrs	PASS
FAN02	Fan, floor, upright	Downstairs	II	OK		>20	Yes	+2yrs	PASS
FAN03	Fan, floor	Downstairs	I	OK	0.169	>20	Yes	+2yrs	PASS
KET09	Kettle	Kitchen	I	OK	0.056	>20	Yes	+2yrs	PASS
TOA01	Toaster	Kitchen	I	OK	0.056	>20	Yes	+2yrs	PASS

PORTABLE APPLIANCE TESTING REPORT

Cordless. Earth check is for base unit. Otherwise all-plastic construction with no visible or touchable metal parts besides element and top trim. Electronic start switch.