Safety Incident Report - Near Miss Forklift Interaction

Manufacturing Knowledge Hub | Production Operations

Owner: Dana Fitzgerald | Last updated: October 30, 2026

Incident report documenting a near-miss between a forklift and a pedestrian aisle crossing, with corrective actions.

Key Points

- Root cause identified limited visibility at the aisle intersection.
- Corrective action added a convex mirror and updated floor marking at the intersection.
- All forklift operators completed a refresher on pedestrian right-of-way rules.
- Follow-up walkthrough scheduled 30 days after corrective actions were implemented.

Source: Manufacturing Knowledge Hub knowledge base | SharePoint Online