

Inspection Report

Checklist, scoring, findings, and corrective actions

Site

Warehouse 12

Inspector

B. Silva

Score

94%

- ☒ Emergency exits clear
- ☒ Electrical panels labeled
- ☐ Forklift lane paint complete
- ☒ Fire extinguishers inspected

Finding	Severity	Action
Lane paint worn	Medium	Repaint by Jan 09
Dock sign faded	Low	Replace sign
Rack labels missing	Low	Print labels