Vehicle Damage Insurance Claim

Driver Information

| Name: | Kristina Mejia |
|---------------|----------------------------------|
| License No: | S90285449 |
| DOB: | 02/01/2066 |
| Address: | Unit 5923 Box 9776, DPO AA 60457 |
| Class: | M |
| Endorsements: | Four Wheeler |

Vehicle Damage Assessment

| Car Make | BMW |
|-----------------------|--|
| Car Model | 3 Series |
| Car Color | Black |
| Damage Details | The front bumper is severely damaged, with the hood and front lights crushed. The front right tire is detached from the rim, and the front left tire is also damaged. The front grille is bent, and the front fender is damaged. |
| Damage Level | high |
| Repair Recommendation | Replace the front bumper, hood, and lights. Repair or replace the front tires. Straighten the front grille and repair the front fender. |
| Claim Value (\$) | \$9,093 |

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Replace the front bumper, hood, and lights. Repair or replace the front tires. Straighten the front grille and repair the front fender.. The estimated severity level is categorized as 'high', with an estimated claim value of \$9,093. Please review and approve for claim processing.