

# Vehicle Damage Insurance Claim

## Driver Information

Name:	Kathleen Lam
License No:	S17200027
DOB:	05/25/2063
Address:	912 Nguyen Field Suite 382, South Carlosburgh, IL 95887
Class:	M
Endorsements:	Four Wheeler

## Vehicle Damage Assessment

Car Make	Volkswagen
Car Model	Golf
Car Color	Blue
Damage Details	The front bumper has a noticeable dent and scratch on the passenger side, extending to the headlight area. The headlight cover appears intact but is slightly misaligned.
Damage Level	medium
Repair Recommendation	Consider getting the bumper and headlight area repainted and repaired to restore the car's appearance and safety. Check for any underlying damage to the headlight assembly.
Claim Value (\$)	\$7,699

## Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider getting the bumper and headlight area repainted and repaired to restore the car's appearance and safety. Check for any underlying damage to the headlight assembly.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$7,699. Please review and approve for claim processing.