

Vehicle Damage Insurance Claim

Driver Information

Name:	David Bruce
License No:	S22210123
DOB:	08/28/2065
Address:	62988 Jill Ports Apt. 597, Joeborough, MO 58463
Class:	M
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Volkswagen
Car Model	Golf
Car Color	White
Damage Details	The rear bumper has a noticeable dent and the rear right tail light is damaged. There are scratches and dents on the rear quarter panel.
Damage Level	medium
Repair Recommendation	Consider replacing the damaged tail light and repairing the dent on the bumper. Assess the scratches and dents on the rear quarter panel for further repair needs.
Claim Value (\$)	\$5,762

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider replacing the damaged tail light and repairing the dent on the bumper. Assess the scratches and dents on the rear quarter panel for further repair needs.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$5,762. Please review and approve for claim processing.