

# Vehicle Damage Insurance Claim

## Driver Information

Name:	Rachel Duke
License No:	S73346391
DOB:	02/09/1969
Address:	225 Robert Hills Suite 966, New Calebmouth, MA 93906
Class:	CDL
Endorsements:	Four Wheeler

## Vehicle Damage Assessment

Car Make	Toyota
Car Model	Yaris
Car Color	Blue
Damage Details	The car has a noticeable dent on the driver's side door and a scratch on the front bumper.
Damage Level	medium
Repair Recommendation	Consider getting the dent and scratch professionally repaired to restore the car's appearance and value. Check for any underlying damage that may require attention.
Claim Value (\$)	\$2,215

## Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider getting the dent and scratch professionally repaired to restore the car's appearance and value. Check for any underlying damage that may require attention.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$2,215. Please review and approve for claim processing.