

# Vehicle Damage Insurance Claim

## Driver Information

Name:	Samuel James
License No:	S94442595
DOB:	06/11/1969
Address:	35786 Katelyn Plaza, East Nicholas, DC 75386
Class:	CDL
Endorsements:	Four Wheeler

## Vehicle Damage Assessment

Car Make	Ford
Car Model	Focus
Car Color	Gray
Damage Details	The rear bumper is detached, and there are scratches on the rear left quarter panel. The rear right tail light is damaged.
Damage Level	medium
Repair Recommendation	Replace the rear bumper, repair the scratches, and replace the damaged tail light. Consider a full inspection for any structural damage.
Claim Value (\$)	\$4,824

## Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Replace the rear bumper, repair the scratches, and replace the damaged tail light. Consider a full inspection for any structural damage.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$4,824. Please review and approve for claim processing.