

Vehicle Damage Insurance Claim

Driver Information

Name:	Scott Jones
License No:	S68833151
DOB:	09/16/2049
Address:	632 Clark Prairie Apt. 365, Richardsonshire, NJ 88143
Class:	CDL
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Seat
Car Model	Ibiza
Car Color	White
Damage Details	The car has a noticeable dent on the rear passenger side door, with scratches extending along the side of the door and into the door panel. The bumper appears to be slightly misaligned.
Damage Level	medium
Repair Recommendation	Consider taking the car to a professional body shop for an assessment and repair of the dent and scratches. Ensure the bumper is realigned if necessary.
Claim Value (\$)	\$6,481

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider taking the car to a professional body shop for an assessment and repair of the dent and scratches. Ensure the bumper is realigned if necessary.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$6,481. Please review and approve for claim processing.