

# Vehicle Damage Insurance Claim

## Driver Information

Name:	Ashley Carter
License No:	S76653966
DOB:	09/29/1973
Address:	120 Singh Locks Apt. 741, Kyleville, CA 56241
Class:	CDL
Endorsements:	Four Wheeler

## Vehicle Damage Assessment

Car Make	Seat
Car Model	Leon
Car Color	White
Damage Details	The car has a dent on the front bumper and a scratch on the side door. The bumper is slightly bent, and the door has a visible scratch.
Damage Level	medium
Repair Recommendation	Consider repairing the dent on the bumper and the scratch on the door. It is advisable to consult a professional for an accurate assessment and repair.
Claim Value (\$)	\$1,872

## Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider repairing the dent on the bumper and the scratch on the door. It is advisable to consult a professional for an accurate assessment and repair.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$1,872. Please review and approve for claim processing.