

Vehicle Damage Insurance Claim

Driver Information

Name:	Karen Jackson
License No:	S44903694
DOB:	04/01/2050
Address:	493 Moore Turnpike, Alexanderland, MT 74299
Class:	CDL
Endorsements:	Four Wheeler

Vehicle Damage Assessment

Car Make	Volkswagen
Car Model	Volkswagen Polo
Car Color	Silver
Damage Details	The car has a significant dent and paint damage on the rear door, with visible scratches and a possible crack in the paint. The bumper appears to be damaged as well.
Damage Level	Medium
Repair Recommendation	Consider taking the car to a professional body shop for a thorough inspection and repair. The dent and paint damage may require panel replacement and repainting.
Claim Value (\$)	\$4,979

Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider taking the car to a professional body shop for a thorough inspection and repair. The dent and paint damage may require panel replacement and repainting.. The estimated severity level is categorized as 'Medium', with an estimated claim value of \$4,979. Please review and approve for claim processing.