

# Vehicle Damage Insurance Claim

## Driver Information

Name:	Gary Gonzalez
License No:	S82514528
DOB:	05/19/1981
Address:	3791 Mckee Common Suite 556, Melissafurt, KS 44942
Class:	D
Endorsements:	Four Wheeler

## Vehicle Damage Assessment

Car Make	Audi
Car Model	A8 L
Car Color	Black
Damage Details	The rear bumper has a noticeable dent on the left side, and there is a scratch on the tail light. There is also a sticker with the letters SRB on the bumper.
Damage Level	medium
Repair Recommendation	Consider repairing the dent and scratch, and possibly replacing the damaged sticker. Check for any underlying damage and ensure the tail light is functioning properly.
Claim Value (\$)	\$4,349

## Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider repairing the dent and scratch, and possibly replacing the damaged sticker. Check for any underlying damage and ensure the tail light is functioning properly.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$4,349. Please review and approve for claim processing.