

# Vehicle Damage Insurance Claim

## Driver Information

Name:	Stephanie Wilson
License No:	S59584871
DOB:	12/27/1969
Address:	4585 David Loaf Suite 705, Andersonchester, MN 20000
Class:	CDL
Endorsements:	Four Wheeler

## Vehicle Damage Assessment

Car Make	Ford
Car Model	Kuga
Car Color	White
Damage Details	The rear bumper has a noticeable dent and paint scrapes. The license plate area also shows signs of impact.
Damage Level	medium
Repair Recommendation	Consider repairing the dent and repainting the affected areas to restore the bumper's appearance and integrity.
Claim Value (\$)	\$8,391

## Claim Summary

This claim report details the damages assessed for the insured vehicle. Based on the inspection, the vehicle requires: Consider repairing the dent and repainting the affected areas to restore the bumper's appearance and integrity.. The estimated severity level is categorized as 'medium', with an estimated claim value of \$8,391. Please review and approve for claim processing.